

Ville de Montréal

**TRUNK SEWER INSPECTION AND
CONDITION ASSESSMENT STUDY**

**Rue McTavish
Rue Ontario
Rue Sainte-Jean-Baptiste**

Project Bonaventure

DRAFT REPORT

**AndrewsInfrastructure
Ottawa, Canada K1M 0P3**

December 2007

Table of Contents

1.0	INTRODUCTION	1-1
1.1	Background	1-1
1.2	Scope	1-1
1.3	Condition Assessment Principles.....	1-1
1.3.1	General.....	1-1
1.3.2	Sediment and Debris.....	1-2
1.3.3	Infiltration.....	1-2
2.0	INSPECTION FINDINGS	2-1
2.1	Overview.....	2-1
2.2	Rue Ontario.....	2-1
2.3	Rue McTavish	2-2
2.4	Rue Sainte-Jean-Baptiste	2-2
2.5	Project Bonaventure	2-4
2.5.1	Saint-Antoine Sewer.....	2-4
2.5.2	De l'inspecteur/Notre Dame Sewer.....	2-5
2.5.3	Notre-Dame, Duke, Gauvin Sewer	2-5
2.5.4	Saint-Maurice and St. Henri.....	2-7
2.5.5	Saint-Paul.....	2-8
2.5.6	Ottawa, Wellington and Dalhousie Sewers	2-8
2.5.7	Nazareth Sewer	2-11
2.5.8	Duke	2-11
2.5.9	Prince Sewer.....	2-12
3.0	CONCLUSIONS AND RECOMMENDATIONS	3-1
3.1	Overview.....	3-1
3.2	General Condition.....	3-1
3.3	Failed Sections	3-1
3.4	Bad Sections – Structural Conditions.....	3-1
3.5	Bad Sections – Service Conditions	3-2
3.6	Rue McTavish	3-3
3.7	General Considerations	3-4

Tables

Table 1-1	Summary of Sewers Inspected	1-2
Table 1-2	Condition Descriptions and Grades	1-3
Table 2-1	Rue Ontario.....	2-1
Table 2-2	Rue McTavish.....	2-3
Table 2-3	Rue Sainte-Jean-Baptiste	2-4
Table 2-4	Saint-Antoine Sewer	2-4
Table 2-5	De l'inspecteur/Notre Dame Sewer	2-5
Table 2-6	Notre-Dame/Duke/Gauvin Sewers.....	2-6
Table 2-7	Saint-Maurice and Saint-Henri.....	2-7
Table 2-8	Saint-Paul.....	2-8
Table 2-9	Ottawa Sewer.....	2-9
Table 2-10	Wellington Sewer	2-9
Table 2-11	Dalhousie Sewer.....	2-10
Table 2-12	Nazareth Sewer.....	2-11
Table 2-13	Duke Sewer.....	2-12
Table 2-14	Prince Sewer.....	2-12
Table 3-1	Sections in Bad Condition – Structural Conditions.....	3-2
Table 3-2	Sections in Bad Condition – Service Conditions	3-3

Figures

Figure 1-1	Location Plan.....	1-5
Figure 2-1	Rue Ontario	2-13
Figure 2-2	Rue McTavish.....	2-15
Figure 2-3	Sainte-Jean-Baptiste.....	2-17
Figure 2-4	Project Bonaventure.....	2-19

1.0 INTRODUCTION

1.1 Background

Inspection and condition assessment of selected sewers were undertaken. In total 1802 m of sewers were investigated. The purpose of this report is to document the inspection findings, present condition grades according to WRc standards and to present recommendations for follow-up action. Manhole inspections were not undertaken.

AndrewsInfrastructure was also retained by Montreal to inspect and assess the William Street and Sherbrooke Street trunk sewers. These sewers are addressed in a separate report dated November 2007.

1.2 Scope

A summary of assets inspected is provided in Table 1-1 and shown schematically in Figure 1-1. Assessment does not include review of documentation related to the construction, maintenance or operation of the assets except as otherwise noted in the report. This inspection and condition assessment report is limited to a visual, surficial survey of the specified sewers.

The nature of this type of study does not lend itself to a clear definition of a geographical study area. Generally the investigations address the actual assets and a narrow corridor following their alignment. Where the asset may impact, or is potentially impacted by the surrounding land uses or environment, the study is locally expanded as appropriate. Throughout this report certain terms have been used which have precise definitions related to the business of inspecting and assessing wastewater collection assets; refer to the Glossary for definitions.

1.3 Condition Assessment Principles

Observations made during the sewer inspections have been documented, or coded, in accordance with conventional WRc standards. Furthermore, each section of sewer has been graded in accordance with WRc criteria. The purpose of this section is to describe the WRc inspection and coding process.

1.3.1 General

In essence, the purpose of this project is to answer the question ‘What remedial action is required today, or in the near future, in order to ensure that the sewer system continues to give an acceptable level of service?’ To answer this question, the inspection findings have been reviewed in the context of the WRc condition grading system and one of the 5 condition grades have been assigned to each asset; these grades are Good, Fair, Poor, Bad or Failed.

The WRc Method is widely used and allows a standardized approach for assessing sewer condition. The method is clearly documented, rigorous and well understood and hence routinely used in numerous Canadian cities especially for large diameter sewer assessment. The standard Condition Grades are listed in Table 1-2. In general, the worse defect, or condition, observed in a particular section of sewer governs the grade for the entire section. A fuller discussion of condition assessment is provided in Appendix A.

Some sewer sections could not be fully inspected for various reasons (for

example, root blockages, heavy silt, rubble or other debris). These sections are noted in the observation tables. Where possible a condition grade has been assigned based on the available observations. It should be noted that further damage or worse conditions may exist in the portion of the sewer not inspected.

1.3.2 Sediment and Debris

Sediment, rubble and debris deposits are typically not related to structural performance (except occasionally in cases of severe structural deterioration). As such, deposits are not explicitly included in the WRc structural condition assessment methodology. None-the-less, sediment deposits and rubble can greatly influence overall system performance and hence can be a trigger to undertake maintenance and repair work. Therefore, in this project debris deposits which influence performance have been factored into the overall condition assessment.

The first level of sediment impact is defined as deposits which are significant enough to negatively influence hydraulic performance but where that influence doesn't extend beyond the particular section of sewer during dry-weather flow conditions. In this case a Fair (or WRc condition rating of 2) is assigned. If the deposit(s) cause an influence beyond the specific section of sewer then a rating of Poor (WRc rating 3) is assigned. If the deposit creates a partial blockage that jeopardizes the ongoing performance of the sewer or is creating sustained overflow conditions then a Bad rating (WRc 4) is assigned. Complete blockage is assigned a Failed rating (WRc rating 5).

Table 1-1 Summary of Sewers Inspected

Sewer	Range	Report Sub-section
Rue Ontario	MH 303-11-079 to MH 303-11-074	2.2
Rue McTavish	MH 303-30-301 to MH 303-30-049	2.3
Rue Sainte-Jean-Baptiste	MH R-407 to MH R-410	2.4
Project Bonaventure		
Saint-Antoine	MH R-100 to MH 303-40-021	2.5.1
De l'inspecteur /Notre-Dame	MH R-118 to MH R-122 MH R-115 to MH R-117 MH R-117 to Raccordment	2.5.2
Notre-Dame/ Duke/ Gauvin	MH R-141 to MH R-161 MH R-143 to Raccordment MH 303-40-239 to Raccordment	2.5.3
Saint-Maurice and Saint-Henri	MH R-145 to MH R-149 Raccordment to Raccordment	2.5.4
Saint-Paul	MH R-150 to MH R-154	2.5.5
Ottawa/Wellington/ Dalhousie	MH R-132 to MH R-135 MH R-196 to MH R-200 MH R-127 to MH R-131	2.5.6
Nazareth	MH R-165 to Raccordment MH R-179 to MH R-174	2.5.7
Duke	MH R-164 to MH R-184	2.5.8
Prince	MH R-136 to MH R-137	2.5.9

1.3.3 Infiltration

Infiltration is the leakage of groundwater into the sewer through defective joints, holes or structural defects (fractures, for example). It is present to some degree in almost all sewers and, among other things, adds to increased hydraulic loading. When assessing the condition or structural performance of a particular trunk


sewer, however, this hydraulic loading of little consequence. Infiltration is more of a concern from a structural point of view in terms of the damage done to bedding and external pipe support. Infiltration can lead to void creation and ultimately to sink hole development.

This later aspect of infiltration, which is an important consideration for condition assessment, is not explicitly considered in the WRc scoring and grading methodology. Therefore, for this project infiltration has been added as a scoreable factor when assigning condition grades. Running infiltration or gushing infiltration at joints is scored such that the sections are graded either Fair or Poor, respectively. Such infiltration at a structural defect, such as a fracture, break or hole will likely result in the section being rated according to the defect (since it will likely be more serious and hence scores higher than the infiltration). Isolated or infrequent occurrences of only dripping and seeping infiltration are scored low such that it will not result in a down-grading of the assigned condition.

Table 1-2 Condition Descriptions and Grades

Grade	Typical Defect Descriptions	Condition	Action
1 Good	No structural defects	Acceptable structural condition	No action required except for regular system maintenance and inspection.
2 Fair	Circumferential cracks Active infiltration Moderate joint defects, open or displaced Spalling slight, Wear slight	Minimal collapse risk in short-term but potential for further deterioration	Re-inspect within 5 years. If condition worsens downgrade to Poor and adjust action plan accordingly.
3 Poor	Fractures with deformation less than 5% Longitudinal cracking or multiple cracking Minor loss of level, moderate infiltration Severe joint defects, open or displaced Spalling medium, Wear medium	Collapse unlikely in short term but further deterioration likely	Develop rehabilitation strategy and incorporate into regular, on-going rehabilitation program.
4 Bad	Broken, deformation up to 10% Fracture with deformation 5 – 10% Heavy infiltration Multiple fractures, serious loss of level Spalling and surface wear (large)	Collapse likely in foreseeable future	Develop rehabilitation strategy and plan for early implementation. Consider options for emergency response.
5 Failure	Collapsed; broken Deformation greater than 10% Extensive, serious infiltration Fracture with deformation greater than 10%	Structural or service failure Collapsed or collapse imminent	Begin process to reconstruct or repair. Prepare emergency response plan and/or temporary measures.

Source: In part from “Sewer Rehabilitation Manual, Volume II”, third edition, pg. 35, Water Research Centre, Marlow, England, 1994; with modifications as described in the text.



2.0 INSPECTION FINDINGS

2.1 Overview

Each sewer is discussed separately in the following sections (see Chapters listed in Table 1-1 for reference). Observations are summarized for each sewer with detailed comments provided in the related tables. Sewer system characteristics are summarized in the Sewer Tables in Appendix B. Condition ratings are shown schematically in Figures 2-1 to 2-4.

2.2 Rue Ontario

General: The sewer comprises a 900 x 600 mm egg shaped brick pipe throughout all sections. The sewer was found to be in Poor to Failed condition. Extensive areas of debris and brick rubble prevented complete inspection of some sections. Detailed inspection observations are provided in Table 2-1 and Figure 2-1. Moderate to severe structural damage was observed including mortar loss, fractures, holes, horizontal and vertical deformation and full collapse. Voids in the surrounding backfill were observed at the collapse area (see photograph 3-1 in Chapter 3). A utility pipe (watermain?) was observed across the sewer obvert which has caused significant damage to the brick fabric.

Table 2-1 Rue Ontario

Sewer Section	Observations	Grade
MH 303-11-079 to MH 303-11-078	900x600 mm Egg shaped Brick, 10 to 45% Water level, D/S, Missing mortar, Bricks missing and displaced, utility pipe (watermain?) through obvert Debris – Rubble 15%, Longitudinal Fracture 12:00 at 25.1 m, Vertical deformation 5%, Hole at 40.7 m, Survey abandoned – camera under water	Bad. Missing bricks, fracture, hole. Partially inspected. (1 Section)
MH 303-11-078 to MH 303-11-077	900x600 mm Egg shaped Brick, 25% Water level, Missing mortar, Bricks displaced Vertical deformation 10%, Longit. fracture 10:00 & 2:00 at 0.8 m, Survey abandoned due to displaced bricks. Partially inspected.	Bad. Missing bricks, fractures. (1 Section)
MH 303-11-077 to MH 303-11-076	D/S 900x600 mm Egg shaped Brick, 20% Water level; Missing Bricks – Void, Horizontal deformation 25%; Survey abandoned due to void from missing bricks U/S 900x600 mm Egg shaped Brick, 15% Water level, Missing mortar, Missing Bricks, Debris – Rubble 5%, Horizontal deformation 10%, Survey abandoned – camera sunk	Failed. Collapsed, deformation, missing bricks. Partially inspected. (1 Section)
MH 303-11-076 to MH 303-11-075	D/S 900x600 mm Egg shaped Brick, 20% Water level Missing mortar, Bricks displaced, Debris – Rubble 15%, Vertical Deformation 5%, Longitudinal fracture 2:00 at 4.6, 15 m, Longitudinal fracture 10:00 at 8.2 m	Poor. Due to fractures, deformation (1 Section)
MH 303-11-075 to MH 303-11-074	D/S 900x600 mm Egg shaped Brick, 10% Water level Encrustation light, Missing mortar, Debris - Rubble 10%, Encrustation medium 10%, Survey abandoned due to medium encrust., U/S 900x600 mm Egg shaped Brick, 25% Water level, Missing Mortar Debris – Rubble 15 to 20%, Survey abandoned due to rubble	Poor. Due to encrustation. Partially inspected. (1 Section)

Service: The water levels were observed between 10 and 45%. The observed structural damage, especially brick rubble, has a direct effect on the hydraulic characteristics and causes back-ups.

2.3 Rue McTavish

General: This sewer comprises three types; 900 x 600 mm egg shaped concrete pipe (2 sections), 900 x 600 mm egg shaped brick pipe (8 sections) and a single 750 mm circular concrete. Detailed inspection observations are provided in Table 2-2 and Figure 2-2. Moderate structural distress was observed. However significant infiltration, including running and gushing infiltration, was observed (see photographs in Chapter 3). Pipe size and material changed in two sections (to 600 mm concrete pipe). These may correspond to previous sewer repairs.

Service: Very fast flow with very clear sewage. Moderate to heavy running and gushing infiltration throughout the upper sewer sections. Infiltrating water is under obvious pressure and in some cases can be seen issuing vertically up through the sewer invert. Mortar has been washed out in some areas with resulting shifted and displaced bricks. Pockets of sediment and rubble were observed in downstream sections. Otherwise sections are clean and well scoured. Water level is relatively constant at about 5% of full pipe. Water levels increase to 50% in the downstream reach in part due to observed sediment and rubble deposits.

2.4 Rue Sainte-Jean-Baptiste

General: This sewer comprises 4 sections of 900 x 600 mm egg shaped brick pipe and one section of 600 mm circular concrete. Detailed inspection observations are provided in Table 2-3 and Figure 2-3. Longitudinal fractures at the crown and some deformation observed (see photograph in Chapter 3). Longitudinal cracks and cracked bricks (shrinkage cracks) observed. This sewer is otherwise structurally sound.

Service: Flow is steady throughout; water levels approximately 5% of full pipe. In the single section of 600mm diameter pipe the water level was between 5 and 30%. Pockets of rubble and debris throughout.

Table 2-2 Rue McTavish

Sewer Section	Observations	Grade
MH 303-30-301 to MH 303-30-300	900x600 mm Egg shaped Concrete, 5% Water level, D/S Debris – Concrete 10%, Sewer deviates down marginal Longitudinal crack 2:00 at 5.9 m, Infiltration running at crack	Fair. Due to infiltration, crack. (1 Section)
MH 303-30-300 to MH 303-30-299	900x600 mm Egg shaped Concrete, 5% Water level D/S Missing mortar, Infiltration running	Poor. Due to infiltration. (1 Section)
MH 303-30-299 to MH 303-30-298	900x600 mm Egg shaped Brick, 5% Water level D/S Missing mortar, Bricks displaced, Sewer deviates left – slight, Infiltration running throughout, Infiltration gushing throughout	Bad. Due to infiltration. (1 Section)
MH 303-30-298 to MH 303-30-297	900x600 mm Egg shaped Brick, 5% Water level D/S Missing mortar, Bricks displaced, Vertical deformation 5% Longitudinal fractures: 12:00 at 2.0, 58.9 m Infiltration running – 2:00 at 51.6 m, 5:00 at 22.2 m, 8:00 at 37.9, 38.9 m, 9:00 at 48.5 m, Gushing infiltration – 5:00 at 5.9, 23.0, 32.1 m, 6:00 at 56.2, 59.2, 61.1, 7:00 at 52.3 m	Bad. Due to fractures, infiltration. (1 Section)
MH 303-30-297 to MH 303-30-296	900x600 mm Egg shaped Brick, 5% Water level D/S Missing bricks, Sewer change: Material – concrete, Shape – concrete, Dimension – 600 mm	Bad. Due to missing bricks. (1 Section)
MH 303-30-296 to MH 303-30-295	900x600 mm Egg shaped Brick, 5% Water level D/S Missing mortar, Bricks displaced, missing, Vertical deformation 5 to 10%, Longitudinal fracture 12:00 at 17.9, Longitudinal crack 10:00 & 2:00 at 49.5 m, Infiltration running at 48.5, dripping at 48.9 m	Bad. Due to missing bricks, fracture, infiltration. (1 Section)
MH 303-30-295 to MH 303-30-294	900x600 mm Egg shaped Brick, 5% Water level, D/S Missing mortar, Missing mortar medium, Bricks displaced Longitudinal fracture 12:00 at 0.1 m, Infiltration dripping at 43.6 m	Poor. Due to fracture. (1 Section)
MH 303-30-294 to MH 303-30-293	D/S 900x600 mm Egg shaped Brick, 5% Water level Missing mortar medium, Bricks displaced, Debris – Rubble 5 to 15%, Longitudinal fracture 12:00 11.8 m U/S 900x600 mm Egg shaped Brick, 15% Water level Debris – 10 to 15%, Survey abandoned due to overlap	Poor. Due to fracture. (1 Section)
MH 303-30-293 to MH 303-30-292	900x600 mm Egg shaped Brick, 10% Water level, U/S Debris – Rubble 5 to 10%, Bricks 10%	Good (1 Section)
MH 303-30-292A to MH 303-30-049	750 mm Circular Concrete, 5 to 50% Water level, D/S Debris – Rubble 10%, Dimension change – 600 mm Uncharted: MH 303-30-292A	Good. (1 Section)

Table 2-3 Rue Sainte-Jean-Baptiste

Sewer Section	Observations	Grade
MH R-407 to MH R-408	D/S 900x600 mm Egg shaped Brick, 5% Water level Debris – Stones 15%, Bricks 10%, Concrete 10% Survey abandoned due to debris U/S 900x600 mm Egg shaped Brick, 5% Water level Survey abandoned – unable to locate MH R-408	Fair. Due to debris. Partially Inspected (1 Section)
MH R-411 to MH R-412	900x600 mm Egg shaped Brick, 5% Water level, U/S Debris – Rubble 25%, Longitudinal fracture 12:00 at 1.4 m	Poor. Due to fracture. (1 Section)
MH R-412 to MH Main	900x600 mm Egg shaped Brick, 5% Water level, D/S Silt 15%	Good. (1 Section)
MH R-408 to MH R-409	U/S 900x600 mm Egg shaped Brick, 5% Water level Encrustation light, Debris – 10% Rubble Survey abandoned due to rubble D/S 900x600 mm Egg shaped Brick, 5% Water level Survey abandoned – unable to locate MH R-408	Fair. Due to encrustation, rubble. Partially Inspected. (1 Section)
MH R-409 to MH R-410	600 mm Circular concrete, 5 to 30% Water level, D/S	Good. (1 Section)

2.5 Project Bonaventure

Sewer sections were inspected in the area surrounding Autoroute Bonaventure. The study area is generally bounded by Rue McGill, on the east, the Lachine Canal on the south, rue Peel on the west Saint Antoine on the north (see Figure 2-4 for layout). The William Street collector sewer traverses the area; this sewer was inspected and reported on in a separate report by AndrewsInfrastructure dated November 2007. Detailed condition assessment findings are shown on Figure 2-4.

2.5.1 Saint-Antoine Sewer

Detailed observations are provided in Tables 2-4. Two separate portions of this sewer were inspected. Two sections of 750 mm concrete pipe west of University Avenue were inspected. Four sections of 1500x750 egg shaped brick sewer were inspected east of University Avenue. Traffic and debris restricted access such that only three of these sections could be inspected. The one concrete section inspected was in good, clean condition. The egg shaped sections inspected showed significant debris and sediment; surveys abandoned due to sediment.

Table 2-4 Saint-Antoine Sewer

Sewer Section	Observations	Grade
MH R-100 to MH R-101	750 mm Circular Concrete, D/S, Survey abandoned – Access restricted by structures and traffic	Not Inspected (1 Section)
MH R-101 to MH R-102	750 mm Circular Concrete, Water level 10%, U/S Debris – Rubble 5%	Good (1 Section)
MH 303-40-022 to MH Section 303-40-021	U/S - 1500x750 mm, Egg shaped Brick, Water Level 10%, Steel lined, Sewer deviates left slight at 21.4 m, Silt 25%, Survey abandoned due to silt D/S - 1500x750 mm, Egg shaped Brick, Water Level 40%, Survey abandon due to high water level and debris Section partially inspected.	Fair. Due to silt. (1 Section)

2.5.2 De l'inspecteur/Notre Dame Sewer

General: These sewers comprise 900x600 and 1200x900 mm egg shaped brick pipes located on Notre Dame Street and De l'inspecteur (see Table 2-5). A four-section branch on Maurice is also addressed here. Detailed inspection observations are provided in Table 2-5. Light encrustation was also observed. Water levels varied from 30 to 45% with silt levels up to 50%.

Table 2-5 De l'inspecteur/Notre Dame Sewer

Sewer Section	Observations	Grade
St. Maurice Branch		
MH R-118 to MH R-119	U/S 900x600 mm Egg shaped Brick, 5% Water Level Missing mortar, Silt 5 to 15%, Sewer deviates right marginal, Survey abandoned due to silt 15% D/S 900x600 mm Egg shaped Brick, 5% Water Level Missing mortar, Silt 15%, Sewer deviates left slight Survey abandoned due to overlap	Fair. (1 Section)
MH R-119 to MH R-122	750 mm Circular Concrete, 5% Water Level, U/S Silt 5 to 25%	Good (3 Section)
Notre Dame Branch		
MH R-115 to MH R-116	U/S 900x600 mm Egg shaped Brick, 5% Water Level Encrustation light, Missing mortar, Silt 10 to 15% Vertical deformation 10%, Longitudinal fracture 12:00 at 5.9 m, Survey abandoned due to silt D/S 900x600 mm Egg shaped Brick, 5% Water Level Missing mortar, Silt 5 to 20%, vertical deformation 5% Longitudinal fracture 12:00 at 5.7 m. Partially inspected.	Poor. Due to fractures & deformation. (1 Section)
MH R-116 to MH R-117	U/S 900x600 mm Egg shaped Brick, 5% Water Level Missing Mortar, Silt 10 to 20%, Vertical deformation 5% Longitudinal fracture 12:00 at 5.7 m Survey abandoned due to silt U/S 900x600 mm Egg shaped Brick, 5% Water Level Survey abandoned no camera access	Partially Inspected. Bad due to fracture, silt. (1 Section)
De l'inspecteur Branch		
MH R-117 to MH R-122	1200x900 mm Egg shaped Brick, 20% Water Level, U/S Missing mortar, Silt 40 to 45%, Survey abandoned - obstructing branch. Partially inspected.	Fair. (1 Section)
MH R-122 to MH R-123	1200x900 mm Egg shaped Brick, 45% Water Level, D/S Encrustation light, Missing mortar, Missing Bricks, Silt 30%, Fine roots, Infiltration gushing 66.8, 70 m, Infiltration dripping 68.2 m, Longitudinal fracture 12:00 at 70 m, Vertical deformation 10%	Bad. Due to infiltration, fracture. (1 Section)
MH R-123 to Raccordment	D/S 1200x900 mm Egg shaped Brick, 40% Water Level Encrustation light, Missing mortar, Missing, displaced Bricks, Silt 40 to 45%, Survey abandoned due to silt U/S 1200x900 mm Egg shaped Brick, 45% Water Level Survey abandoned – no camera access Section only partially inspected.	Bad. Due to missing bricks and silt. (1 Section)

2.5.3 Notre-Dame, Duke, Gauvin Sewer

Detailed observations are provided in Table 2-6. These sewers comprise 900 x 600 mm egg shaped brick pipe with five sections of 900 mm concrete pipe. The concrete pipe is in Good and Fair condition with pockets of silt. The brick sewers have missing mortar, displaced and missing bricks, encrustation and horizontal and vertical deformation. Extensive encrustation blocked equipment. Fine root intrusions and silt deposits (5 to 35%). Depth of flow from 5 to 10%.

Table 2-6 Notre-Dame/Duke/Gauvin Sewers

Sewer Section	Observations	Grade
Notre Dame/Duke Street Branch		
MH R-141 to MH R-142	900x600 mm Egg shaped Brick, 5% Water Level, D/S Missing Mortar, Fine roots, Silt 5 to 15%, Horizontal Deformation 15% Partially inspected. Survey abandoned due to horizontal deformation	Poor. Due to deformation. (1 section)
MH R-142 to MH R-143	U/S 900x600 mm Egg shaped Brick, 5% Water Level Missing mortar, Bricks missing, displaced, Silt 35% Survey abandoned due to silt. U/S 900x600 mm Egg shaped Brick, 10% Water Level Encrustation light, medium 10%, Missing mortar, Silt 15%, Survey abandoned due to medium encrustation Section only partially inspected.	Bad. Missing bricks, encrustation. (1 Section)
MH R-141 to MH R-158	900 mm Circular Concrete, 5% Water level, U/S Silt 0 to 30%, Longitudinal Crack 12:00 at 38.2 m	Fair. Due to crack. (1 Section)
MH R-158 to MH R-145	900 mm Circular Concrete, 5% Water level, U/S Sewer deviates right - slight	Good. (1 Section)
MH R-145 to MH R-161	900 mm Circular Concrete, 5 to 15% Water level, Debris – Rubble 5 to 20%	Good. (3 Section)
Notre Dame/McGill Branch		
MH R-143 to MH R-144	D/S 900x600 mm Egg shaped Brick, 10% Water Level Encrustation light, Missing mortar, Bricks displaced, Silt 15%, Vertical displacement 10% at 2.7 m, Horizontal displacement at 25.3 m, Longitudinal fracture 12:00 at 41.6 m, Survey abandoned due to debris U/S 900x600 mm Egg shaped Brick, 5% Water Level Missing mortar, Bricks displaced, Silt 15%, Root mass 25%, Survey abandoned due to root mass Section only partially inspected.	Poor due to fracture and displacement. (1 Section)
MH R-144 to Raccordment	D/S 900x600 mm Egg shaped Brick, 10% Water Level Missing mortar, Missing Bricks, Silt 5 to 15% Survey abandoned due to intruding connection U/S 900x600 mm Egg shaped Brick, 5% Water Level Survey abandoned due to lack of camera access Section only partially inspected.	Fair. (1 Section)
Gauvin		
MH 303-40-239 to Raccordment	D/S 900x600 mm Egg shaped Brick, 5% Water level Missing mortar, Missing bricks, Silt 5 to 65%, Vertical Deformation 5%, Longitudinal fracture 12:00 at 39.8 m, Survey abandoned due to silt U/S 900x600 mm Egg shaped Brick, 5% Water level Survey abandoned inaccessible from main sewer	Partially inspected. Bad due to fracture, missing bricks. (1 Section)

2.5.4 Saint-Maurice and St. Henri

General: Detailed observations are provided in Table 2-7. These sewers comprise 600 and 750 mm concrete pipe and two sections of 900 x 600 brick egg-shaped pipe. Six of the ten sections were found to be in Good or Fair condition. The remaining sections were found to be either in Poor or Bad condition. In these sections various degrees of sediment and rubble were observed. Silt levels of 5 to 15% were common with one section rising to 45%. Several surveys were abandoned due to heavy silt deposits (up to 45% of depth). Several longitudinal fractures, missing mortar and missing bricks were also observed.

Table 2-7 Saint-Maurice and Saint-Henri

Sewer Section	Observations	Grade
St. Maurice Branch		
MH R-145 to MH R-146	750 mm diameter Concrete, 5 % Water Level, D/S	Good (1 Sections)
MH R-146 to MH R-147n	750 mm diameter Concrete, 5 % Water Level, D/S Debris – Rubble 5%, Silt 5%	Fair. (1 Section)
MH R-147 to MH R-148	D/S 750 mm diameter Concrete, 0 to 20% Water Level Debris – rubble 10%, silt 5 to 45% Survey abandoned due to silt 45% U/S 750 mm diameter Concrete, 5% Water Level Silt 20 to 45%, Survey abandoned due to silt 45%	Bad. Due to silt. (1 Section)
MH R-148 to MH R-149	750 mm diameter Concrete, 0 to 20% Water Level, D/S Debris – Small stones 10%, Silt 5 to 10 %	Good. (1 Section)
St. Henri Branch		
Raccordment to MH R-155	D/S, 900x600 mm Egg shaped Brick, 5% Water level Missing mortar, Silt 10%, Sewer deviates down – slight Survey abandoned – camera stuck in invert Partially inspected.	Fair. (1 Section)
MH R-155 to MH R-155A	D/S, 900x600 mm Egg shaped Brick, 0% Water level Missing mortar, Silt 10%, Survey abandoned U/S, 900x600 mm Circular Brick, 5% Water level Missing Mortar, Sewer deviates left, right – slight Debris – rubble 10%, brick 10%, Survey abandoned due to Bricks 10%; Partially inspected.	Fair. (1 Section)
MH R-155A to MH R-148	600 mm diameter Concrete, 5% Water level, D/S Debris – Concrete 10%	Good. (1 Section)
Raccordment to MH R-156	600 mm Circular Brick, 0% Water level, D/S Silt 85%, Survey abandoned due to silt Partially inspected	Bad. Due to silt. (1 Section)
MH R-156 to MH R-157	D/S 600 mm Circular Brick, 0% Water level Silt 85%, Survey abandoned due to silt U/S 600 mm Circular Brick, 5% Water level Missing mortar – med., Silt 15 to 25%, Debris – Rubble 15%, Brick 5%, Bricks displaced, missing, Longitudinal fracture 12:00 at 1.4 m, Vertical Deformation 10%, Defective connection 32.2 m, Survey abandoned due to defective connection	Bad. Due to missing bricks, fracture. (1 Section)
MH R-157 to Raccordment	D/S 600 mm Circular Brick, 5% Water level Missing mortar, Missing Bricks, Sewer deviates left – slight, Sewer change: Material – vitrified clay, Dim. – 300mm, Survey abandon due to dimension change U/S 600 mm Circular Brick, 5% Water level No access from main line, partially inspected	Poor. Due to missing bricks. (1 Section)

2.5.5 Saint-Paul

Detailed observations are provided in Table 2-8. This reach comprises 900x600 mm egg shaped Brick sewer. All sections showed some degree of structural distress including missing bricks, fractures and deformation. Two sections (MH R-152 to MH R-154) have collapsed segments (see photographs in Chapter 3). Extensive portions of the brick fabric have fallen away exposing large voids outside the pipe wall. Brick debris has fallen into the invert causing partial flow blockage. Pockets of sediment and rubble elsewhere in these sections.

Table 2-8 Saint-Paul

Sewer Section	Observations	Grade
MH R-150 to MH R-151	D/S 900x600 mm Egg shaped Brick, 10% Water Level Missing mortar, Silt 30 to 40%, Survey abandoned due to silt U/S 900x600 mm Egg shaped Brick, 5% Water Level Encrustation light, Missing mortar, Missing bricks, Silt 25 to 45%, Fine roots, Survey abandoned due to silt	Bad. Due to encrustation, roots and silt. (1 Section)
MH R-151 to MH R-152	D/S 900x600 mm Egg shaped Brick, 5% Water Level Missing mortar, Missing bricks, Silt 25 to 30%, Survey abandoned due to silt U/S 900x600 mm Egg shaped Brick, 15% Water Level Missing mortar, Silt 25 to 30%, Survey abandoned due to silt. Partially inspected.	Bad Due to missing bricks. (1 Section)
MH R-152 to MH R-153	D/S 900x600 mm Egg shaped Brick, 10 to 45% Water Level, Encrustation light, Missing Mortar, Missing bricks, Silt 25 to 30%, Debris – Rubble 40% (collapse), Survey abandoned due to rubble U/S 900x600 mm Egg shaped Brick, 10% Water Level; Missing mortar, Silt 20 to 25%, Survey abandoned due to silt. Partially inspected.	Failed. Due to collapse. (1 Section)
MH R-153 to MH R-154	D/S 900x600 mm Egg shaped Brick, 10% Water Level; Missing mortar, Silt 20 to 25%, Survey abandoned due to silt 25% U/S 900x600 mm Egg shaped Brick, 10% Water Level, Missing mortar, Silt 20 to 25%, Survey abandoned due to silt Partially inspected.	Failed. Due to missing mortar silt. (1 Section)

2.5.6 Ottawa, Wellington and Dalhousie Sewers

The Ottawa Street, Wellington Street and Dalhousie Street sewers comprise a 900 x 600 mm egg shaped brick pipe. Detailed inspection observations are provided in Tables 2-9, 2-10 and 2-11 respectively. Structural distress observed in the form of fractures, missing brick fabric and vertical deformation. Sections rated in Poor condition due to fractures and deformation. Heavy silt deposits up to 35 to 55% of full pipe prevented completion of surveys. Encrustation observed in some segments. Missing mortar observed throughout. Water levels vary from 5 to 10% level.

Table 2-9 Ottawa Sewer

Sewer Section	Observations	Grade
MH R-132 to MH Mur	900x600 mm Egg shaped Brick, 5% Water Level, D/S Encrustation light, Missing mortar, Missing bricks, Silt 15%	Bad. Due to missing bricks (1 Section)
MH R-132 to MH R-133	D/S 900x600 mm Egg shaped Brick, 5% Water Level Missing mortar, Missing Bricks, Silt 25 to 45% Dimension change – 450 mm, Survey abandoned due to silt and dimension change U/S 900x600 mm Egg shaped Brick, 5% Water Level Survey abandoned – No camera access	Bad. Due to missing bricks. (1 Section)
MH R-133 to MH R-134	900x600 mm Egg shaped Brick, 5% Water Level, D/S Encrustation light, Missing, mortar, Debris – Rubble 10%, Vertical deformation 5%, Longitudinal fracture 12:00 at 2.9	Poor. Due to fracture and deformation. (1 Section)
MH R-134 to MH R-135	900x600 mm Egg shaped Brick, 0% Water Level, D/S Missing mortar, Silt 40% Survey Abandoned due to silt. Partially inspected.	Poor. Missing mortar (1 section)

Table 2-10 Wellington Sewer

Sewer Section	Observations	Grade
MH R-196 to MH R-197	900x600 mm Egg shaped Brick, 10% Water Level, D/S Encrustation light, Missing mortar, Missing, displaced bricks, Vertical deformation 10%, Survey abandoned intruding connection Partially inspected	Bad Due to missing bricks, deformation (1 Section)
MH R-197 to MH R-198	D/S 900x600 mm Egg shaped Brick, 5% Water Level Missing mortar, Missing bricks, Silt 30 to 40% Survey abandoned due to silt. U/S 900x600 mm Egg shaped Brick, 5% Water Level Missing mortar, Silt 5 to 15%, Vertical deformation 5% Sewer deviates left – slight, Longitudinal fracture 12:00 at 1.4 m. Partially inspected.	Bad Due to fracture and deformation. 1 (Section)
MH R-196 to MH R-199	D/S 900x600 mm Egg shaped Brick, 0% Water Level No access due to traffic U/S 900x600 mm Egg shaped Brick, 5% Water Level Missing mortar, Silt 35%, Survey abandoned by silt. Partially inspected.	Fair Due to missing mortar, silt. (1 Section)
MH R-199 to MH R-200	D/S 900x600 mm Egg shaped Brick, 5% Water Level Missing mortar, Silt 35%, vertical deformation, 5% Longitudinal fracture 12:00 at 1.4 m, Survey abandoned due to silt. Partially inspected.	Poor Due to fracture and deformation. (1 Section)

Table 2-11 Dalhousie Sewer

Sewer Section	Observations	Grade
MH R-127 to MH R-128	No access to MHs due to traffic.	Not Inspected
MH R-128 to MH R-129	U/S - 900x600 mm Egg shaped Brick, 5% Water level, Missing Mortar, Silt 35%, Vertical deformation 5% Longitudinal fracture 12:00 at 1.4 m D/S - 900x600 mm Egg shaped Brick, 5% Water level, Survey abandoned – no access due to traffic Partially Inspected	Poor. Due to fracture, deformation. (1 Section)
MH R-129 to MH R-130	D/S - 900x600 mm Egg shaped Brick, 5% Water level, Missing manhole, Vertical deformation 5% Longitudinal fracture 12:00 at 1.4 m, Survey abandoned due to silt 35% U/S - 900x600 mm Egg shaped Brick, 5% Water level, Encrustation light, Missing mortar, Silt 5 to 15% Survey abandoned due to silt Partially Inspected.	Poor Due to fracture, deformation. (1 Section)
MH R-130 to MH R-131	900x600 mm Egg shaped Brick, 5% Water level, D/S, Encrustation light, Missing mortar, Silt 10% Sewer deviates right – slight	Fair. Due to missing mortar (1 Section)

2.5.7 Nazareth Sewer

This sewer comprises a 900 x 600 mm egg shaped brick pipe. Detailed inspection observations are provided in Table 2-9. Heavy silt deposits throughout. Deposits reach 90% of full pipe; these sections rated in Bad condition due to silt. Other sections had silt deposits up to 45% of full pipe; these sections rated in Fair condition. Silt deposits prevented complete inspection of most sections. Missing mortar was observed in those sections inspected. Water levels vary from 5 to 10%. Light to heavy pockets of encrustation observed.

Table 2-12 Nazareth Sewer

Sewer Section	Observations	Grade
MH R-165 to MH R-166	900x600 mm Egg shaped Brick, 5% Water level, U/S Silt up to 90%, Survey abandoned due to silt Partially inspected.	Bad. Due to Silt. (1 Section)
MH R-166 to MH R-169	900x600 mm Egg shaped Brick, 5% Water level, U/S Silt up to 90%, Survey abandoned due to silt Partially inspected.	Bad. Due to Silt. (3 Sections)
MH R-170 to MH R-173	900x600 mm Egg shaped Brick, 5% Water level, U/S Debris, silt and rubble up to 35%, Survey abandoned due to silt and rubble	Fair Due to debris (3 Section)
MH R-173 to MH R-174	900x600 mm Egg shaped Brick, 10% Water level, MH R-173 – Could not locate MH MH R-174 – Unable to access MH	Not inspected.
MH R-174 to MH R-177	900x600 mm Egg shaped Brick, 10% Water level, missing mortar, Silt up to 35% in places.	Fair Due to debris (4 Sections)
MH R-177 to MH R-178	900x600 mm Egg shaped Brick, 15% Water level Missing mortar, Encrustation light to heavy (greater than 10% blockage), Debris, rubble and silt up to 30%; Survey abandoned due to heavy encrustation Partially inspected.	Fair Due to heavy encrustation, silt. (1Section)
MH R-178 to Raccordment	900x600 mm Egg shaped Brick, 15% Water level, D/S, Missing mortar, sewer deviates right - slight	Fair. Due to missing mortar. (1 section)
Dalhousie Branch		
MH R-179 to MH R-180	900 x 600 mm Egg shaped Brick, 0% Water Level, D/S Survey Abandoned – no access to R-179	Not Inspected.
MH R-180 to MH R-181	900 x 600 mm Egg shaped Brick, 0% Water Level; Missing mortar, Silt 30 to 55%, Sewer Change to 600 mm circular concrete; Survey abandoned due to silt; Partially inspected.	Fair due to silt. (1 Section)
MH R-181 to MH R-201	900x600 mm Egg shaped Brick, 5% Water Level, U/S Missing mortar, Silt 30%	Fair. Missing mortar (1 Section)
MH R-201 to MH R-174	U/S 900x600 mm Egg shaped Brick, 10% Water Level; Missing mortar, Silt 35 to 40%	Fair. Due to silt. (1 Section)

2.5.8 Duke

General: This sewer comprises 900 x 600 mm egg shaped brick pipe. Detailed inspection observations are provided in Table 2-13. Heavy structural deterioration observed including fractures, deformation and infiltration. Sections rated in Poor and Bad condition due to the observed distress. Water levels were consistent throughout at 5%. Silt levels varied from 15 to 40%.

Table 2-13 Duke Sewer


Sewer Section	Observations	Grade
MH R-164 to MH R-163	D/S 900x 600 mm Egg shaped Brick, 5% Water level Missing mortar, Silt 25 to 30%, Vertical deformation 5%, Longitudinal fracture 12:00 at 34.8 m, Survey abandoned due to silt U/S 900 mm Egg shaped Brick, 5% Water level Encrustation light, Missing mortar, Silt 20 to 25% Survey abandoned due to silt	Poor. Due to fracture. (1 Section)
MH R-163 to MH R-162	D/S 900 mm Egg shaped Brick, 5% Water level Missing mortar, Debris – Concrete 10%, Silt 15% Longitudinal frac.12:00 at 1.4 m, Survey abandoned due to concrete 10% U/S 900 mm Egg shaped Brick, 5% Water level Encrustation light, Missing mortar up to medium, Missing bricks, Debris – Concrete 10%, Silt 5 to 30%, Vertical deformation 5%, Longitudinal fracture 12:00 at 6.9, 48.5, 65.4 m, Survey abandoned due to overlap	Bad. Due to fractures, deformation. (1 Section)
MH R-162 to Recordment	D/S 900 mm Egg shaped Brick, 5% Water level Encrustation light, medium 10%, Missing mortar, Silt 15 to 40%, Infiltration running, vertical deformation 10%, Longitudinal fracture 12:00 at 0.0, 13.9, 39.4 m, Survey abandoned due to silt U/S 900 mm Egg shaped Brick, 5% Water level Inaccessible from main sewer	Poor. Due to fractures, deformation. (1 Section)
MH R-182 to MH R-184	500 mm Circular Concrete, 0% Water level Surveys not undertaken due to inaccessible MHs	Not Inspected. (2 sections)

2.5.9 Prince Sewer

General: This single section sewer comprises 900 mm circular PVC and 900 x 600 mm egg shaped brick pipe. Detailed inspection observations are provided in Table 2-14. The short distance of PVC pipe contained a fracture and deformation. Missing mortar, fractures, deformation and encrustation were observed in the downstream portion of brick sewer. Water levels varied from 5 to 25%; silt levels varied from 25 to 35%.

Table 2-14 Prince Sewer

Sewer Section	Observations	Grade
MH R-136 to MH R-137	900 mm, Circular PVC, 5 to 25% Water level, D/S, Encrustation light, Missing mortar, Silt 25 to 30% Sewer Change: Shape – Egg, Diameter – 900x600 mm, Material – Brick, Longitudinal fracture – 12:00 at 1.4 m, 2:00 at 29.2 m, Survey abandoned due to silt.	Bad. Due to fractures. (1 Section)



LEGEND


- Sewer & MH Not Inspected
- Sewer & MH in Good Condition
- Sewer & MH in Fair Condition
- Sewer & MH in Poor Condition
- Sewer & MH in Bad Condition
- Sewer & MH in Failed Condition

Montréal 
 Plan d'intervention des réseaux
 d'aqueduc et d'égouts

INSPECTION CCTV - SONAR

RUE ONTARIO

FIGURE 2-1



LEGEND


- Sewer & MH Not Inspected
- Sewer & MH in Good Condition
- Sewer & MH in Fair Condition
- Sewer & MH in Poor Condition
- Sewer & MH in Bad Condition
- Sewer & MH in Failed Condition

Montréal
 Plan d'intervention des réseaux
 d'aqueduc et d'égouts

INSPECTION CCTV - SONAR

RUE McTAVISH

FIGURE 2-2



LEGEND

- Sewer & MH Not Inspected
- Sewer & MH in Good Condition
- Sewer & MH in Fair Condition
- Sewer & MH in Poor Condition
- Sewer & MH in Bad Condition
- Sewer & MH in Failed Condition

Montréal 
 Plan d'intervention des réseaux
 d'aqueduc et d'égouts

INSPECTION CCTV - SONAR

**RUE
 SAINTE-JEAN-BAPTISTE**

FIGURE 2-3

3.0 CONCLUSIONS AND RECOMMENDATIONS

3.1 Overview

Conclusions and recommendations related to specific types of defects are discussed in the following sections. Several general considerations are discussed in Section 3.7.

3.2 General Condition

Over the years, Andrews Infrastructure has compiled an extensive database of large diameter trunk sewer condition statistics. These statistics are based on sewers inspected using the WRC method across Canada. A statistical summary for sewer sections with sizes between 600 and 900 mm diameter (and for all ages) shows that 75% to 85% of all sections are typically in Good or Fair condition. This finding is generally true for all pipe sizes and pipe materials. Typically less than 1% of all sections are either in Bad or Failed condition. By comparison, results in this study shows that fully 40% of the sections inspected are in Bad or Failed condition. Furthermore, only 43% are in Good or Fair condition.

3.3 Failed Sections

Three sewer sections were found to be in an advanced state of structural deterioration including complete pipe failure in the following locations:

- Rue Ontario MH 303-11-077 to 303-11-076 (Photograph 3-1)
- Rue St. Paul MH R-152 to R-153 (Photograph 3-2)
- Rue St. Paul MH R-153 to R-154 (Photograph 3-3)

In addition to the actual failures in these sections, there is also other extensive structural deterioration including fractures, displaced bricks, missing brick fabric and structural deformation. In these areas the structures are not stable. Given the age of the sewer there is a high degree of soil consolidation in the sewer envelope and hence, even in the failed areas the road structure has stayed intact. In the areas of advanced deterioration the structure remains standing. However, as is usually the case with sewers, any unrelated, random change in the area (such as a watermain break) could trigger soil envelope failure and road surface collapse. The timing of an event that could trigger such a failure can not be predicted.

It is recommended that the highest priority be given to reconstructing or rehabilitating these sections that have failed. Prior to repair, the City should be prepared for the possible sudden failure of the road surfaces at one or more of these sections.

3.4 Bad Sections – Structural Conditions

Numerous sewer sections were rated in Bad condition due to extensive structural damage. These are listed in Table 3-1. Structural damage includes longitudinal fractures and deformation (5% to 10%, more in some cases, see Photograph 3-5), missing mortar, missing bricks, missing brick fabric and active infiltration. As with the previously noted Failed sections, these sewer sections remain standing due to the heavily consolidated soil envelopes. However, significant random

events could disturb this soil envelope and trigger a complete failures. Sudden road surface collapses can not be ruled out in these areas.

It is recommended that a comprehensive rehabilitation program be developed and implemented for these sewers (as listed in Table 3-1). This program should consider the benefit of complete reconstruction versus rehabilitation, on a case by case basis. Where adjoining sewer sections are in Poor condition, these adjoining sewers should be included in the program. It is understood that significant road re-construction works are planned for Autoroute Bonaventure. Careful consideration should be given as to how the damaged sewers can be best addressed during this road reconstruction work. Assessment of drainage patterns and drainage needs should also be assessed. Opportunities to separate combined sewers, re-direct flow, or to construct new sewers, should be assessed in order to allow for abandonment of some of the badly damaged sections.

Table 3-1 Sections in Bad Condition – Structural Conditions

Sewer Section	Sewer Details	Street
MH 303-11-079 to 303-11-078	900x600 mm Egg shaped Brick	Rue Ontario
MH 303-11-078 to 303-11-077	900x600 mm Egg shaped Brick	Rue Ontario
MH 303-30-299 to 303-30-298	900x600 mm Egg shaped Brick	Rue McTavish
MH 303-30-298 to 303-30-297	900x600 mm Egg shaped Brick	Rue McTavish
MH 303-30-297 to 303-30-296	900x600 mm Egg shaped Brick	Rue McTavish
MH 303-30-296 to 303-30-295	900x600 mm Egg shaped Brick	Rue McTavish
MH 303-30-299 to 303-30-298	900x600 mm Egg shaped Brick	Rue Sainte-Jean-Baptiste
MH 303-30-298 to 303-30-297	900x600 mm Egg shaped Brick	Rue Sainte-Jean-Baptiste
MH 303-30-297 to 303-30-296	900x600 mm Egg shaped Brick	Rue Sainte-Jean-Baptiste
MH 303-30-296 to 303-30-295	900x600 mm Egg shaped Brick	Rue Sainte-Jean-Baptiste
MH R-122 to R-123	1200x900 mm Egg shaped Brick	De l'inspecteur Branch
MH R-142 to R-143	900x600 mm Egg shaped Brick	Notre Dame/Duke St Branch
MH 303-40-239 to Reccordment	900x600 mm Egg shaped Brick	Gauvin
MH R-147 to R-148	750 mm diameter Concrete	St. Maurice Branch
MH R-116 to R-117	900x600 mm Egg shaped Brick	Notre Dame Branch
MH R-156 to R-157	600 mm Circular Brick	St. Henri Branch
MH R-151 to R-152	900x600 mm Egg shaped Brick	Saint-Paul
MH R-132 to Mur	900x600 mm Egg shaped Brick	Ottawa Sewer
MH R-132 to R-133	900x600 mm Egg shaped Brick	Ottawa Sewer
MH R-196 to R-197	900x600 mm Egg shaped Brick	Wellington Sewer
MH R-197 to R-198	900x600 mm Egg shaped Brick	Wellington Sewer
MH R-163 to R-162	900 mm Egg shaped Brick	Duke Sewer
MH R-136 to R-137	900 mm diameter PVC	Prince Sewer

3.5 Bad Sections – Service Conditions

Numerous sections were found to be in Bad condition due to heavy silt and rubble accumulations. The depth and extent of the observed debris seriously impacts hydraulic performance (see Photographs 3-3 and 3-6). Due to the depth of sediment, many of these sections could not be fully inspected with CCTV equipment. As a result additional defects, in the form of moderate to serious structural defects, could exist, undetected, in some of these sections. Typically a comprehensive cleaning program would be indicated. However, given the risk of worsening existing damage in these sewers, routine cleaning with high pressure

flushers or bucket equipment should not be undertaken without careful, continuous monitoring.

Therefore it is recommended that a selective cleaning program be implemented. Individual sections should be selected for careful cleaning and monitoring. Continuous CCTV inspection, for example, would be needed as the cleaning progresses to ensure no additional structural damage is caused. Alternatively, given the widespread structural damage observed in the Project Bonaventure area, consideration could be given to simply including these sewers in the previously recommended rehabilitation program. Reconstructing some sections may in fact be less costly than cleaning and/or rehabilitation. It should be kept in mind that likely many of these sections will reveal significant structural distress once cleaned.

Table 3-2 Sections in Bad Condition – Service Conditions

Sewer Section	Pipe Specifics	Street
MH R-123 to Raccordment	1200x900 mm Egg shaped Brick	De l'inspecteur Branch
MH R-147 to R-148	750 mm diameter Concrete	St. Maurice Branch
Raccordment to MH R-156	600 mm Circular Brick	St. Henri Branch
MH R-150 to R-151	900x600 mm Egg shaped Brick	Saint-Paul
MH R-165 to R-166	900x600 mm Egg shaped Brick	Nazareth Sewer
MH R-166 to R-167	900x600 mm Egg shaped Brick	Nazareth Sewer
MH R-167 to R-168	900x600 mm Egg shaped Brick	Nazareth Sewer
MH R-168 to R-169	900x600 mm Egg shaped Brick	Nazareth Sewer

3.6 Rue McTavish

The rate of infiltration and apparent groundwater pressure along the McTavish sewer is remarkable. The pressure of the infiltrating water causes gushing water in the invert to divert flow in the sewer. Water can be seen coming up through the invert in Photograph 3-4. Mortar has been washed out of some joints with resulting displaced bricks. Extensive cracks and fractures are frequent. The incoming water is clear. The sewage itself is unusually clear. It is understood that the City's water supply reservoir is located adjacent to the sewer.

It is recommended that investigations be carried out at first opportunity to confirm the nature and source of the high groundwater pressures. It is further recommended that the sections of the McTavish sewer currently in Bad condition be rehabilitated or reconstructed in order to alleviate the infiltration issues. It should be confirmed that the groundwater pressures will not be transferred to other underground services once the sewer is repaired. Furthermore the potential for leakage from the reservoir should be assessed. It is noted that the heavy infiltration tends to occur along the east side of the sewer or in the sewer invert. Continuation of this infiltration could lead to significant bedding washout and eventual collapse of the sewer fabric. Sewer failure and road collapse in this area could have catastrophic consequences for the reservoir foundations and general slope stability along McTavish. The existence of voids around the sewer can not be ruled out and hence it is suggested that the recommended investigations be carried out at the first opportunity.

3.7 General Considerations

It is recognized that regular inspection of larger sewers and trunks, and other high risk assets, is critical in terms of good long term maintenance. Given that there are no comprehensive previous inspection data with which to compare, *it is recommended that the City consider regular re-inspection of these assets on a 10-year or 5-year cycle for the sewers found to be in Good or Fair condition respectively.* Many of the conclusions and recommendations made in this report are time dependent; they represent a 'snap-shot' of the condition of the asset only at the time of inspection. Advance warning of new or on-going deterioration, or any changes in condition for that matter, can only be predicted and managed through regular re-inspection.

AndrewsInfrastructure

**Per: Mark Andrews, P.Eng.
Project Manager**

This report has been prepared by AndrewsInfrastructure for the City of Montreal and reflects best judgement in light of the information available at the time of preparation and in the context of the specific project requirements. The report focuses on the defined scope of work in terms of the needs and requirements of the City and as a result it does not necessarily reflect the needs of any other parties. AndrewsInfrastructure does not accept responsibility for damages, if any, suffered by any third party as a result of decisions made or actions undertaken by them based on this report. The conclusions made herein are based on field conditions which may have been valid only at the time of inspection and hence may be subject to change.

GLOSSARY

Adjuster ring: Rings, usually made of brick or pre-cast concrete, set directly below the frame and cover; used to adjust the level of the frame and cover to the road or ground surface grade.

Chimney: The part of a manhole located between the roof of the chamber and ground level; usually made of brick or precast rings.

Condition: Five defined states reflecting the relative state of preservation of the asset being considered; five states are Good, Fair, Poor, Bad, and Failed (see further explanation in Appendix).

Crack: A structural defect that penetrates the surface of the pipe wall (but does not extend through the entire wall thickness).

Fracture: A structural defect that passes completely through the pipe wall hence creating a discontinuity in the structure which can allow groundwater to enter the pipe.

Location: A site in the sewer and is referenced by the distance from the upstream manhole (unless it is noted that the survey proceeded in the upstream direction in which case the distance is measured from the downstream manhole).

Position: A point on the wall of the pipe at a particular *location* and is referenced by a 12-hour clock notation.

Section: A portion of a sewer between two consecutive manholes.


Segment: A portion of a *section* usually defined by chainage.

Wash Zone: The part of the wetted perimeter of the pipe between the normal (diurnal) high water line and normal highest (wet weather) water line. In *sections* effected by H₂S related corrosion the *wash zone* is often much less damaged due to infrequent washing away of corrosive material.

Photograph 3-1

Collapsed sewer with voids at both springlines (Ontario St., MH 303-11-077 to MH 303-11-076)

148



Photograph 3-2

Collapsed sewer with void (St. Paul, MH R-152 to R-153)

142



Photograph 3-3

Collapsed sewer with void (St. Paul, MH R-154 to R-153)


146



Photograph 3-4

Running and gushing infiltration


128



Photograph 3-5

Fractures and Vertical deformation (> 10%)


160



Photograph 3-6

Debris in sewer (> 25%)

172



APPENDIX A

Condition Assessment

APPENDIX A

RISK ASSESSMENT AND CONDITION CODES

A.1 Risk of Failure

A.1.1 Introduction

The conventional approach to assessing the condition of sewers is to review and consider the observed condition of only the pipe itself. This approach is appropriate for the vast majority of sewers where the required level of performance and the installation situation is well understood and generally uniform. In the case of large diameter sewers, trunk sewers in particular, where there can be widely ranging installation conditions, environmental sensitivities, a large number of nearby utilities, important transportation corridors, and large differences in construction techniques and soil conditions, this conventional approach may not necessarily be sufficient.

In the case of these sewers an integrated approach is thought to be more in keeping with the importance of the sewer. That is, it is necessary to consider all aspects of the sewer when it comes to making decisions regarding its maintenance and upkeep. More specifically, in addition to the basic structural condition of the pipe it is necessary to consider local soil conditions, interrelationship with adjacent utilities, potential for traffic disruptions and possible effects on nearby above-ground structures.

The purpose of assessing the condition of these sewers is to determine the risk associated with failure and the associated potential effects, or consequences, of failure. The following sections outline the various factors that influence the operation of the systems, the possible modes of failure, and the approach used to assign risk levels; all of which must be considered in an integrated approach. A description of the method used to establish a condition class for each section of the sewer inspected is provided in a subsequent section.

It should be remembered that the conclusions and recommendations made in this report are based on actual observations made. In general, for any sewer where observations suggest that the structure is in good condition, it is presumed that the sewer is at

the lowest level of risk that is possible to determine. Of course, that is not to say that the apparently good sewer may not fail in the very near future for some reason that was undetectable at the time of inspection. As a result, the recommendations put forward in this report can only address the observed deficiencies. There is always an overriding risk that some other unanticipated factor could influence the condition of the sewer and may determine the actual risk of failure. Subsequent, more detailed, investigations should help to identify and control this additional risk.

A.1.2 Failure

Failure is defined to include the following three scenarios.

Worst case: Complete and sudden collapse of the sewer. Consequences definitely include substantial or complete blockage of flow at least at one point on a continuous basis for a prolonged period of time. Initially, all sewage flows would be bypassed untreated to local surface waters and could result in widespread basement flooding. Consequences may also include extreme soil voids, excessive surface settlement and sink holes, utility breaks and/or traffic disruption.

Partial blockage: Progressive distortion of the sewer causing some reduction in hydraulic capacity. Such events may not be sudden and could occur over an extended length of time. Partial blockage could ultimately lead to complete collapse of the sewer. Partial blockage could involve periodic wastewater discharge to surface waters; the severity and frequency of discharge being dependant on the degree of blockage. The factors contributing to partial blockage could also lead to void creation, settlement, utility breaks, and traffic disruption which could be as severe as that encountered in the worse case.

Indirect failure: Sewer remains intact while adjacent soil or surface failure occurs. A possible indirect failure mode involves the creation of soil voids due to washing of fine particles into the sewer through infiltration. Severe surface settlements,

utility breaks, and traffic disruptions could occur with consequences as severe as the worse case but with little or no impact on the sewer itself or on hydraulic capacity.

A.1.3 Risk Analysis and Condition Rating

Two aspects of risk need to be considered when assessing the condition of the trunk sewer. Firstly, it is necessary to determine what level of risk of failure is associated with a particular condition in the sewer. Secondly, it is necessary to establish what level of risk is acceptable in order to make decisions regarding the need to address the specific conditions.

A recent literature search indicated that little research has been done in terms of compiling and quantifying failures of large diameter sanitary sewers. Less has been done to quantify the risk associated with failure under certain conditions. Further, it appears that no attempt has been made to establish in a quantitative way the level of risk that is acceptable. As a result it is considered appropriate in this report to treat risk in a qualitative rather than quantitative way.

The approach used to assess the condition of the sewers in this report involves the assignment of a condition grade according the WRc methodology. The grades are 'bumped-up' in some cases to reflect specific concerns. Issues related to risk are then assessed and, in combination with the WRc rating, an overall Condition Grade is assigned to the section of sewer. This approach represents a slight modification or enhancement of the WRc method, and is based in part on work done by the Greater Chicago District (Macaitis, 1994). An indication of the relationship between the condition grade, the WRc Grade and observed characteristics is provided in the text of the report.

Four levels of risk have been assumed.

Nominal Risk: In cases where no evidence of structural distress is seen it can be assumed that the structure is at the lowest level of risk of failure. Although there may be no evidence of distress there is likely some risk of failure since there could be factors effecting the structure which generate no tell tale signs. Therefore, the notion of negligible or 'zero' risk is not used since the actual level of risk is never known. In this assessment report this lowest level of risk is termed "Nominal Risk". These sewers are referred to as being in 'good' condition.

Elevated Risk: Two factors can lead to elevated risk. Firstly, obvious tell tale signs of distress can indicate increased risk of failure. These can include cracks, fractures, heavy infiltration, cross-sectional distortion, etc. Observation of any of these conditions in the sewer indicates an elevated level of risk of failure. These sewers are referred to as being in 'fair' condition.

Secondly, independent of the sewer structure itself, the area in which the sewer is located can lead to situations of elevated risk. For example, poor soil conditions, excessive utility usage and congestion, and areas of unusually heavy loading can lead to increased risk of failure. In such cases, a rating of 'fair' may be given even though 'good' may have otherwise been assigned.

Highly Elevated Risk: This level of risk would occur when a section of sewer with advanced deterioration (elevated level of risk of failure) and/or is located in a high risk area. In these cases a rating of 'poor' is assigned.

Unacceptable Risk: When a section of sewer is observed to be in an advanced stage of distress and is located in a high risk area, the risk of failure is considered to be unacceptable. A rating of Bad is applied here.

A.1.4 Condition Codes

Observed defects have been recorded following the WRc codes for service and structural defects as provided in the following two tables:

Table A-1 Service Defects

Code	Description	Code	Description
CU	Camera underwater	IS	Infiltration seep
DE	Debris	OB	obstruction
DEG	Debris grease	OBJ	Obstruction at joint
DES	Debris silt	REM	Remarks
EH	Encrustation heavy	RF	Roots fine
EL	Encrustation light	RFJ	Roots fine at joint
EM	Encrustation medium	RM	Roots mass
ESH	Scale heavy	RMJ	Roots mass at joint
ESL	Scale light	RS	Repaired section
ESM	Scale medium	RT	Roots tap
FH	Finish survey	RTJ	Roots tap at joint
GO	General observation	SA	Survey abandoned
GP	General photograph	ST	Start of survey
ID	Infiltration dripper	V	Vermin
IG	Infiltration gusher	WL	Water level
IR	Infiltration runner		

Table A-2 Structural Defects

Code	Description	Code	Description
B	Broken pipe	JDL	Joint displaced large
BJ	Broken pipe at joint	JDM	Joint displaced medium
BR	Branch (major)	JDS	Joint displaced slight
CC	Crack circumferential	JN	Junction
CCJ	Crack circumferential at joint	JX	Junction defective
CL	Crack longitudinal	LC	Lining change
CM	Crack longitudinal at joint	LD	Line deviates down
CN	Connection	LL	Line deviates left
CNI	Connection intruding	LR	Line deviates right
CX	Connection defective	LU	Line deviates up
CXI	Connection defective intruding	MC	Material change
D	Deformation	MH	Manhole
DC	Diameter change	OJL	Open joint large
FC	Fracture circumferential	OJM	Open joint medium
FL	Fracture longitudinal	PC	Pipe length change
FM	Fracture longitudinal at joint	SC	Shape change
H	Hole	SS	Surface spalling
HSH	Hydrogen sulphide heavy	SW	Surface wear
HSL	Hydrogen sulphide light	X	Collapse
HSM	Hydrogen sulphide medium		

Table A-7 Definition of States

State	Condition	Action	Description
1	Good	Do nothing	That is, do nothing less than regular maintenance
2	Fair	Monitor	Monitor to ensure that either there is no further deterioration or if there is downgrade to state 3.
3	Poor	Investigate	Investigate further to confirm if the situation is not as bad as thought in which case upgrade to state 2, or if situation proves problematic downgrade to state 4.
4	Bad	Plan to repair /reconstruct	Planning relies in part on the sort of investigation needed in State 3 and involves determining whether to repair, rehabilitate, or totally reconstruct and the appropriate level of effort and timing. Planning also involves determining whether the works need to take place in the near future or longer term or whether the works can be delayed in order to take advantage of other planned works.
5	Failure	Repair /reconstruct	Here the works are to be undertaken without delay. Once the type of work is established, the level of effort determined and design completed the works are immediately commenced. If through the course of developing options it is discovered that some delay is tolerable then by definition upgrade to State 4.

APPENDIX B
Sewer Summary Tables

Additional Inspections									
U/S MH	D/S MH	Size	Type	Plan Length	Survey Length	DVD #	Survey #	Date Inspected	Condition Rating
Saint-Antoine									
R-100	R-101	600x900		57.0	0.0		170/171	11-Nov-07	NI
R-101	R-102	750		26.0	24.8	18	169	11-Nov-07	Good
303-40-022	303-40-021	1500		77.0	31.9	18	167/168	11-Nov-07	Fair
Section Length:				160.00	56.7				
Notre-Dame									
R-141	R-142	600x900		46.0	13.2	14	82	7-Nov-07	Fair
R-142	R-143	600x900		88.0	10.1	14	83/84	7-Nov-07	Bad
R-143	R-144	600x900		99.0	8.3m	14	85/86	7-Nov-07	Bad
R-144	Raccordment	600x900		61.0	8.8	14	87/88	7-Nov-07	Bad
R-115	R-116	600x900		50.0	7.6	14	89	8-Nov-07	Bad
R-116	R-117	600x900		68.0	12.7	14	90/91	8-Nov-07	Bad
Section Length:				412.00	134.9				
Saint Maurice									
R-118	R-119	600x900		40.0	39.7	13	75/76	7-Nov-07	Fair
R-119	R-120	750		10.0	9.4	13	72	6-Nov-07	Good
R-120	R-121	750		38.0	37.4	13	73	6-Nov-07	Good
R-121	R-122	750		16.0	14.8	13	74	6-Nov-07	Good
R-145	R-146	750		18.0	13.0	13	68	5-Nov-07	Good
R-146	R-147	750		93.0	91.7	13	67	5-Nov-07	Fair
R-147	R-148	750		103.0	69.7	13	69/70	5-Nov-07	Bad
R-148	R-149	750		37.0	39.8	13	71	5-Nov-07	Good
Section Length:				355.00	315.5				
Saint-Paul									
R-150	R-151	600x900		47.0	42.7	15	110/111	9-Nov-07	Bad
R-151	R-152	600x900		45.0	11.7	15	108/109	9-Nov-07	Bad
R-152	R-153	600x900		92.0	26.5	15	105/107	9-Nov-07	Failed
R-153	R-154	600x900		89.0	74.8	15	104/106	9-Nov-07	Failed
Section Length:				273.00	155.7				
Ottawa									
R-132	Mur	600x900		36.0	28.9	16	124	10-Nov-07	Bad
R-132	R-133	600x900		35.0	31.2	16	125/128	10-Nov-07	Bad
R-133	R-134	600x900		40.0	34.5	16	126	10-Nov-07	Poor
R-134	R-135	600x900		27.0	0.2	16	127	10-Nov-07	Poor
Section Length:				138.00	94.8				

U/S MH	D/S MH	Size	Type	Plan Length	Survey Length	DVD #	Survey #	Date Inspected	Condition Rating
Wellington									
R-181	R-201	600x900		10.0	2.9	18	148	10-Nov-07	Fair
R-201	R-174	600x900		58.0	66.8	18	146/147	10-Nov-07	Fair
R-196	R-197	600x900		69.0	24.4	18	155	10-Nov-07	Bad
R-197	R-198	600x900		56.0	12.7	18	156/157	10-Nov-07	Bad
R-196	R-199	600x900		97.0	1.9	18	152/154	10-Nov-07	Fair
R-199	R-200	600x900		86.0	1.9	18	153/158	10-Nov-07	Poor
Section Length:				376.00	110.6				
De l'inspecteur									
R-117	R-122	800x1200		13.0	7.1	14	93	8-Nov-07	Fair
R-122	R-123	800x1200		85.0	84.9	14	92	8-Nov-07	Bad
R-123	Raccordment	800x1200		75.0	10.2	14	94/95	8-Nov-07	Bad
Section Length:				173.00	102.2				
Dalhousie									
R-179	R-180	600x900		53.0	0.0		151	10-Nov-07	NI
R-180	R-181	600x900		36.0	11.6	18	149/150	10/11/2007	Fair
R-127	R-128	600x900		18.0	0.0		120/121	09/11/2007	NI
R-128	R-129	600x900		54.0	3.9	16	117/119	09/11/2007	Poor
R-129	R-130	600x900		123.0	15.0	16	118/122	09/11/2007	Poor
R-130	R-131	600x900		23.0	16.3	16	123	10/11/2007	Fair
Section Length:				307.0	46.8				
Nazareth									
R-165	R-166	450		10.0				10/11/2007	NI
R-166	R-167	600x900		79.0	0.1	18	161	10/11/2007	Bad
R-167	R-168	600x900		167.0	0.2	18	160/162	10/11/2007	Bad
R-168	R-169	500		19.0	0.1	18	163	10/11/2007	Bad
R-170	R-171	750		36.0	1.4	14	96	08/11/2007	Fair
R-171	R-172	450		11.0	1.1	14	98	08/11/2007	Fair
R-171	R-173	750		42.0	3.4	14	97	08/11/2007	Fair
R-173	R-174	600x900		63.0	0.0		159	10/11/2007	Ni
R-174	R-175	600x900		10.0	10.4	17	145	10/11/2007	Fair
R-175	R-176	600x900		67.0	66.8	17	144	10/11/2007	Fair
R-176	R-133	600x900		83.0	91.3	16/17	129/143	10/11/2007	Fair
R-133	R-177	600x900		45.0	4.8	16/17	130/142	10/11/2007	Fair
R-177	R-178	600x900		85.0	35.3	17	140/141	10/11/2007	Fair
R-178	Raccordment	600x900		15.0	10.5	17	139	10/11/2007	Fair
Section Length:				732.0	225.4				

U/S MH	D/S MH	Size	Type	Plan Length	Survey Length	DVD #	Survey #	Date Inspected	Condition Rating
Autoroute Bonaventure									
R-182	R-183	750		54.0	0.0		164	11/11/2007	NI
R-183	R-184	750		60.0	0.0		165/166	11/11/2007	NI
Section Length:				114.0	0.0				
Duke									
R-141	R-158	750		61.0	59.2	13	81	07/11/2007	Fair
R-158	R-145	900		18.0	9.2	13	80	07/11/2007	Good
R-145	R-159	900		70.0	78	13	77	07/11/2007	Good
R-159	R-160	900		84.0	83.9	13	78	07/11/2007	Good
R-160	R-161	900		7.0		6.8	79	07/11/2007	Good
R-164	R-163	600x900		77.0	76.6	17	133/134	10/11/2007	Poor
R-163	R-162	600x900		99.0	99.1	17	135/136	10/11/2007	Bad
R-162	Raccordment	600x900		83.0	52.9	17	137/138	10/11/2007	Poor
Section Length:				499.0	458.9				
Prince									
R-136	R-137	600x900		88.0	34.5	16	116	09/11/2007	Bad
Section Length:				88.0	34.5				
Gauvin									
303-40-239	Raccordment	600x900		82.0	58.5	15	114/115	09/11/2007	Bad
Section Length:				82.0	58.5				
Saint-Henri									
R-155	Raccordment	600x900		31.0	17.1	15	112	09/11/2007	Fair
R-155	R-155A	600x900		56.0	40.8	17	131	10/11/2007	Fair
R-155A	R-148	600x900		14.0	15.0	16	132	10/11/2007	Good
R-156	Raccordment	300		13.0	0.1	14	99	08/11/2007	Bad
R-156	R-157	600		55.0	32.3	15	100/101	08/11/2007	Bad
R-157	Raccordment	600		10.0	3.0	15	102/103	08/11/2007	Poor
Section Length:				179.0	108.3				
Combined Section Length				3666.0	1902.8				

Rue Ontario									
U/S MH	D/S MH	Size	Type	Plan Length	Survey Length	DVD #	Survey #	Date Inspected	Condition Rating
303-11-079	303-11-078	900			44.9	10	40/47	27-28/10/2007	Bad
303-11-078	303-11-077	900			1.8	10	41/48	28-Oct-07	Bad
303-11-077	303-11-076	900			9.8	10	42/43	28-Oct-07	Failed
303-11-076	303-11-075	900			18.3	10	44	28-Oct-07	Poor
303-11-075	303-11-074	900			24.7	10	45/46	28-Oct-07	Poor
Section Length:					99.5				
Rue McTavish									
U/S MH	D/S MH	Size	Type	Plan Length	Survey Length	DVD #	Survey #	Date Inspected	Condition Rating
303-30-301	303-30-300	900			46.9	10	49	29-Oct-07	Fair
303-30-300	303-30-299	900			41.2	10	50	29-Oct-07	Poor
303-30-299	303-30-298	900			78.9	10	51	29-Oct-07	Bad
303-30-298	303-30-297	900			81.2	11	52	29-Oct-07	Bad
303-30-297	303-30-296	900			8.4	11	53	29-Oct-07	Bad
303-30-296	303-30-295	900			56.9	11	54	29-Oct-07	Bad
303-30-295	303-30-294	900			91.9	11	55	29-Oct-07	Poor
303-30-294	303-30-293	900			48.1	11	56/59	29-30/10/2007	Poor
303-30-292	303-30-049	750			28.5	11	57	30-Oct-07	Good
303-30-292	303-30-293	900			20.8	11	58	30-Oct-07	Good
Section Length:					502.8				
Rue Sainte-Jean-Baptiste									
U/S MH	D/S MH	Size	Type	Plan Length	Survey Length	DVD #	Survey #	Date Inspected	Condition Rating
R-407	R-408	900			24.9	11	60/66	30-Oct-07	Fair
R-412	R-411	900			15.8	11	61	30-Oct-07	Poor
R-412	R-Main	900			6.3	11	62	30-Oct-07	Good
R-409	R-410	600			6.2	12	63	30-Oct-07	Good
R-409	R-408	900			36.2	12	64/65	30-Oct-07	Fair
Section Length:					89.4				
Combined Section Length					691.7				

APPENDIX C
Sewer Coding Sheets

0H1C33986/AN 303-11-079X 40
 0H22710070130 RUE ONTARIO
 CITY OF MONTREAL
 0H3303-11-079 303-11-078
 0H4CD 900 600EBR 0449Z
 0H50010
 0H6A3B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-11-079
 0D1 000.0 WL 10
 0D1 001.5S1MS 0804
 0D1 001.5 CN 15003
 0D1 003.0 BR 600X450
 0D1 004.1 CNI 15010 0025
 0D1 007.0 MB1101PIPECROSSCROWN
 0D1 008.3 CNI 8004 0050
 0D1 008.3 CNI 8008 0050
 0D1 011.7 BR900X600CLEANRUBBLE
 0D1 013.2 GO PIPE ACROSS CROWN
 0D1 019.3 DB 03
 0D1 025.1S2FL 12
 0D1 025.1S3DV 05
 0D1 027.9 CN 15008 LIVE
 0D1 028.7 DE 10 RUBBLE
 0D1 028.7F3DV 05
 0D1 030.7 DB 12
 0D1 036.6 CN 20004 LIVE
 0D1 037.2 CX 22508
 0D1 037.2 CN 30004 SEALED OFF
 0D1 039.9 CN 15009
 0D1 039.9 WL 30
 0D1 040.7 H 03
 0D1 040.7 CN 15009
 0D1 040.7S4DE 15 RUBBLE
 0D1 041.4 CN 22510
 0D1 044.9 WL 45
 0D1 044.9F1MS 0705
 0D1 044.9F2FL 12
 0D1 044.9F4DE 15 RUBBLE
 0D10223 044.9 SA CAMERAUNDERWATER

0H1C33986/AN 303-11-078X 41
 0H22810072130 RUE ONTARIO
 CITY OF MONTREAL
 0H3303-11-077 303-11-078
 0H4CU 900 600EBR 0018Z
 0H50010
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-11-077
 0D1 000.0 WL 25
 0D1 000.8S1DE 15 RUBBLE
 0D1 000.8S2FL 10
 0D1 000.8S3FL 02
 0D1 000.8 MT 0710
 0D1 000.8 MT 0205
 0D1 000.8 DB 0710
 0D1 000.8 DB 0205
 0D1 000.8S4DV 10
 0D1 001.8 DB 10
 0D1 001.8F1DE 05
 0D1 001.8F3FL 10
 0D1 001.8F2FL 02
 0D1 001.8F4DV 10
 0D10082 001.8 SA DUE TO DB

0H1C33986/AN 303-11-077X 42
 a1=MPEG_A_10282007_2204_43_1113i.mp2
 0H2281007 RUE ONTARIO
 CITY OF MONTREAL
 0H3303-11-077 303-11-076
 0H4CD 900 600EBR 0025Z
 0H50010
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-11-077
 0D1 000.0 WL 20
 0D1 000.1S1MB 0710 VOID
 0D1 000.1S2MB 0205 VOID
 0D1 000.1S3DH 25
 0D1 002.5F1MB 0710
 0D1 002.5F2MB 0205
 0D1 002.5F3DH 25
 0D10033 002.5 SA DUE TO MB VOID

0H1C33986/AN 303-11-077X 43
 a1=MPEG_A_10282007_2259_44_1123i.mp2
 0H22810072259 RUE ONTARIO
 CITY OF MONTREAL
 0H3303-11-076 303-11-077
 0H4CU 900 600EBR 0073Z
 0H50010
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-11-076
 0D1 000.0 WL 15
 0D1 001.5S1MB 0708
 0D1 001.5S2MS 0804
 0D1 001.5S3DE 05 RUBBLE
 0D1 001.5S4DH 10
 0D1 002.0F1MB 0708
 0D1 002.0F2MS 0804
 0D1 002.0F3DE 05 RUBBLE
 0D1 002.0F4DH 10
 0D10091 007.3 SA CAMERA STUCK

0H1C33986/AN 303-11-076X 44
 0H22810072313 RUE ONTARIO
 CITY OF MONTREAL
 0H3303-11-076 303-11-075
 0H4CD 900 600EBR 0183Z
 0H50010
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-11-076
 0D1 000.0 WL 10
 0D1 001.5S1MS 0804
 0D1 001.5S2DE 15 RUBBLE
 0D1 004.6 CN 10001
 0D1 004.6S3FL 02
 0D1 004.7S5DV 05
 0D1 008.2 CN 22502
 0D1 008.2S4FL 10
 0D1 009.5 CNI 15003 0010
 0D1 011.3 CX 22509 SEALED
 0D1 014.3F3FL 02
 0D1 014.3F4FL 10
 0D1 014.3F5DV 05
 0D1 015.0 FL 02
 0D1 015.0 MT 02
 0D1 015.0 DB 02
 0D1 018.3F1MS 0804
 0D1 018.3F2DE 15 RUBBLE
 0D1 018.3 MH 303-11-075
 0D1 018.3 FH

0H1C33986/AN 303-11-075X 45
 0H22810072331 RUE ONTARIO
 CITY OF MONTREAL
 0H3303-11-075 303-11-074
 0H4CD 900 600EBR 0127Z
 0H50010
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-11-075
 0D1 000.0 WL 10
 0D1 000.1S1MS 0804
 0D1 000.1S2DE 10 RUBBLE
 0D1 000.2S3EL 0804
 0D1 002.7 CNI 22511 0010LIVE
 0D1 003.3 CNI 22502 0010LIVE
 0D1 010.1 CXI 15011 0015SEALED
 0D1 012.7 EM 030510
 0D1 012.7 EM 070810
 0D1 012.7F1MS 0804
 0D1 012.7F2DE 10 RUBBLE
 0D1 012.7F3EL 0804
 0D10071 012.7 SA DUE TO EM 10%

0H1C33986/AN 303-11-075X 46
 0H22810070115 RUE ONTARIO
 CITY OF MONTREAL
 0H3303-11-074 303-11-075
 0H4CU 900 600EBR 0120Z
 0H50010
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-11-074
 0D1 000.0 WL 25
 0D1 001.5S1MS 0804
 0D1 001.5S2DE 15 RUBBLE
 0D1 002.2 WL 40
 0D1 003.2 CN 22504 LIVE
 0D1 012.0C2DE 20 RUBBLE
 0D1 012.0F1MS 0804
 0D1 012.0F2DE 20 RUBBLE
 0D10071 012.0 SA DE 20% RUBBLE

0H1C33986/AN 303-11-079X 47
 0H22810070142RUE ONTARIO
 CITY OF MONTREAL
 0H3303-11-078 303-11-079
 0H4CU 900 600EBR 0000Z
 0H5
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-11-078
 0D1 000.0 WL 15
 0D10000 000.0 SA UNABLETOSETUP JN

0H1C33986/AN 303-11-078X 48
 0H22810070144 RUE ONTARIO
 CITY OF MONTREAL
 0H3303-11-078 303-11-077
 0H4CD 900 600EBR 0000Z
 0H5
 0H6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH 303-11-078
 OD1 000.0 WL 15
 OD10000 000.0 SA UNABLETOSETUP JN

0H1C33986/AN 303-30-301X 49
 0H22910070242 RUE MCTAVISH
 CITY OF MONTREAL
 0H3303-30-301 303-30-300
 0H4CD 900 600ECO 1000469Z
 0H50010
 0H6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH 303-30-301
 OD1 000.0 WL 05
 OD1 004.7 CX 15001
 OD1 005.9 CL 02
 OD1 013.8 CXI 15001 0075
 OD1 013.8 LD MARGINAL
 OD1 014.6 DE 10 CONCRETE
 OD1 022.9 IRJ 04
 OD1 028.1 CXI 8001 0050
 OD1 029.0 CXI 15001 0050SEALED
 OD1 035.6 IRJ 0305
 OD1 046.9 MH 303-30-300
 OD10105 046.9 FH

0H1C33986/AN 303-30-300X 50
 a1=MPEG_A_10292007_0357_51_1209i.mp2
 0H2291007 RUE MCTAVISH
 CITY OF MONTREAL
 0H3303-30-300 303-30-299
 0H4CD 900 600ECO 1000412Z
 0H50010
 0H6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH 303-30-300
 OD1 000.0 WL 05
 OD1 001.5 CXI 30011 0050
 OD1 017.9 CXI 22511 0025
 OD1 025.7 CX 22501
 OD1 026.0 MM 0105
 OD1 026.4 MT 0305
 OD1 026.4 IR 03
 OD1 028.1 CN 30002 LIVE
 OD1 041.2 MH 303-30-299
 OD10074 041.2 FH

0H1C33986/AN 303-30-299X 51
 0H22910070407 RUE MCTAVISH
 CITY OF MONTREAL
 0H3303-30-299 303-30-298
 0H4CD 900 600EBR 0789Z
 0H50010
 0H6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH 303-30-299
 OD1 000.0 WL 05
 OD1 004.0 MT 07
 OD1 004.0 IR 07
 OD1 006.7 IG 06
 OD1 009.6S1IG 06
 OD1 012.9 CN 22501
 OD1 012.9 IR 07
 OD1 013.2 MT 08
 OD1 013.2 IR 08
 OD1 013.2F1IG 06
 OD1 016.1 CN 15001
 OD1 017.1 CN 22511
 OD1 023.7 CX 22501POSS SEALED
 OD1 024.1 MT 08
 OD1 024.1 IR 08
 OD1 024.1 DB 0810
 OD1 030.3 CX 10001 LIVE
 OD1 036.6 CX 22511
 OD1 038.4 LL SLIGHT
 OD1 040.5 IG 05
 OD1 041.3 MT 0405
 OD1 041.3 IG 05
 OD1 046.4S2IG 08
 OD1 046.4S3MT 08
 OD1 051.7F2IG 08
 OD1 051.7F3MT 08
 OD1 051.7 MT 09
 OD1 051.7 IG 09
 OD1 051.7S4IR 10
 OD1 051.7S5MT 10
 OD1 052.4 MT 10
 OD1 052.4 IG 10
 OD1 053.6 MT 10
 OD1 053.6 IG 10
 OD1 058.2F5MT 10
 OD1 058.2F4IR 10
 OD1 061.3 MT 03
 OD1 061.3 IR 03
 OD1 061.3 CX 22501
 OD1 064.7 MT 03
 OD1 064.7 IG 03
 OD1 069.3 CX 22502 LIVE
 OD1 078.9 MH 303-30-298
 OD1 078.9 FH

0H1C33986/AN 303-30-298X 52
 0H22910070437 RUE MCTAVISH
 CITY OF MONTREAL
 0H3303-30-298 303-30-297
 0H4CD 900 600EBR 0812Z
 0H50011
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-30-298
 0D1 000.0 WL 05
 0D1 001.9 CX 15011
 0D1 002.9S1FL 12
 0D1 002.9S2DV 05
 0D1 005.9 MT 05
 0D1 005.9 IG 05
 0D1 011.0F1FL 12
 0D1 011.0F2DV 05
 0D1 013.7 CN 22501 LIVE
 0D1 022.2 MT 05
 0D1 022.2 IR 05
 0D1 023.0S3MT 05
 0D1 023.0S4IG 05
 0D1 023.7 DB 0710
 0D1 030.9 CN 22501 LIVE
 0D1 032.1F3MT 05
 0D1 032.1F4IG 05
 0D1 032.1 CN 22511
 0D1 037.4 DB 0104
 0D1 037.9 MT 0809
 0D1 037.9 IR 08
 0D1 037.9 DB 0709
 0D1 038.9 MT 08
 0D1 038.9 IR 08
 0D1 038.9 DB 0709
 0D1 038.9S5FL 12
 0D1 048.5 MT 09
 0D1 048.5 IR 09
 0D1 048.9 CN 22502 LIVE
 0D1 051.6 MM 02
 0D1 051.6 IR 02
 0D1 051.6F5FL 12
 0D1 052.3 IG 07
 0D1 052.3 MT 07
 0D1 056.2 IG 06
 0D1 056.2 CN 15011
 0D1 059.5 IG 06
 0D1 059.5 MT 06
 0D1 061.1 IG 06
 0D1 066.9 CN 22501 LIVE
 0D1 074.2 CNI 22511 0050
 0D1 076.9 CN 22501
 0D1 081.2 MH 303-30-297
 0D10243 081.2 FH

0H1C33986/AN 303-30-297X 53
 0H22910070506 RUE MCTAVISH
 CITY OF MONTREAL
 0H3303-30-297 303-30-296
 0H4CD 900 600EBR 0084Z
 0H50011
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-30-297
 0D1 000.0 WL 05
 0D1 006.6 CX 45011
 0D1 006.6 MB 1101
 0D1 006.6 MC CONCRETE
 0D1 006.6 DC 600
 0D1 006.6 SC CIRCULAR
 0D1 008.4 MH 303-30-296
 0D10041 008.4 FH

0H1C33986/AN 303-30-296X 54
 a1=MPEG_A_10292007_2135_56_1325i.mp2
 0H22910072124 RUE MCTAVISH
 CITY OF MONTREAL
 0H3303-30-296 303-30-295
 0H4CD 900 600EBR 0569Z
 0H50011
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-30-296
 0D1 000.0 WL 05
 0D1 000.0 CL 02
 0D1 007.0 CN 22511
 0D1 007.3 CN 22511
 0D1 008.7 CX 15001
 0D1 009.7 MB 0710
 0D1 009.7 CX 30011 LIVE
 0D1 011.5 CN 22501
 0D1 012.4 CN 22502
 0D1 014.4 CN 22501 SEALED OFF
 0D1 015.5 CN 22502
 0D1 017.9S1FL 12
 0D1 017.9S2DV 05
 0D1 017.9S3MT 12
 0D1 020.0 CNI 22504 0075LIVE
 0D1 020.8 CNI 15004 0050
 0D1 032.0 CN 15001 SEALED OFF
 0D1 037.4 CX 22511
 0D1 040.2 DB 12
 0D1 045.5 MT 10
 0D1 045.5 MT 10
 0D1 048.5 IR 10
 0D1 048.9 ID 10
 0D1 049.5 CN 15001
 0D1 049.5S4CL 10
 0D1 049.5S5CL 02
 0D1 049.5C2DV 10
 0D1 053.3 CX 22511
 0D1 055.3 CX 22501 SEALED OFF
 0D1 056.9F1FL 12
 0D1 056.9F2DV 10
 0D1 056.9F3MT 02
 0D1 056.9F5CL 10
 0D1 056.9F5CL 02
 0D1 056.9 MH 303-30-295
 0D10205 056.9 FH

0H1C33986/AN 303-30-295X 55
 0H22910072158 RUE MCTAVISH
 CITY OF MONTREAL
 0H3303-30-295 303-30-294
 0H4CD 900 600EBR 0919Z
 0H50011
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-30-295
 0D1 000.0 WL 05
 0D1 000.1S1FL 12
 0D1 000.1S2MS 0705
 0D10000 000.1S3MT 12
 0D1 002.7 CN 22501
 0D1 003.6 MM 0710
 0D1 003.6 CN 22511
 0D1 009.7 CX 22501 SEALED OFF
 0D1 016.6 CN 15001
 0D1 017.1 CN 22511
 0D1 020.6F1FL 02
 0D1 020.6F3MT 12
 0D1 027.8 CN 22501
 0D1 039.3 CN 30002 LIVE
 0D1 040.5 CN 22501
 0D1 043.6 ID 02
 0D1 044.0 CN 22501 LIVE
 0D1 044.9 CN 22501 LIVE
 0D1 045.4 CXI 25001 0050LIVE
 0D1 046.3 MM 0711
 0D1 046.3 CX 22511
 0D1 047.4 CN 22501
 0D1 047.8 CN 22501
 0D1 053.0 CN 22501
 0D1 066.3 CN 22511
 0D1 072.3 CN 22501
 0D1 081.6 CNI 30002 0050LIVE
 0D1 088.4 DB 0205
 0D1 088.4 MM 0205
 0D1 088.4 CNI 15001 0075LIVE
 0D1 091.9F2MS 0705
 0D1 091.9 MH 303-30-294
 0D10211 091.9 FH

0H1C33986/AN 303-30-294X 56
 0H22910072246 RUE MCTAVISH
 CITY OF MONTREAL
 0H3303-30-294 303-30-293
 0H4CD 900 600EBR 0448Z
 0H50011
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-30-294
 0D1 000.0 WL 05
 0D1 001.0 CNI 15001 0075LIVE
 0D1 008.9 MM 0105
 0D1 008.9 CN 15001 LIVE
 0D1 011.8S1FL 12
 0D1 013.9F1FL 12
 0D1 016.7 CN 15001
 0D1 025.0 DB 01
 0D1 025.0 CX 15001
 0D1 036.0 CN 15001
 0D1 037.6 CNI 10011 0025LIVE
 0D1 037.6 CN 22511
 0D1 040.4 CN 22501
 0D1 040.9 CX 15002 SEALED OFF
 0D1 040.9S2DE 05 RUBBLE
 0D1 042.3 CX 22502 SEALED OFF
 0D1 043.1 CX 30003 LIVE
 0D1 043.2C2DE 10 RUBBLE
 0D1 044.8C2DE 15 RUBBLE
 0D1 044.8F2DE 15 RUBBLE
 0D10151 044.8 SA DE 15% RUBBLE

0H1C33986/AN 303-30-292X 57
 0H23010070037 RUE MCTAVISH
 CITY OF MONTREAL
 0H3303-30-292 303-30-049
 0H4CD 750 CCO 2500285Z
 0H50011 MH NOS WRONG ON DVD
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-30-292
 0D1 000.0 WL 05
 0D1 004.1 GO UNCHRT MH30-293A
 0D1 005.6 DC 600
 0D1 006.9S1DE 10 RUBBLE
 0D1 006.9 WL 35
 0D1 015.0 JN 30010 LIVE
 0D1 015.7 JN 30001 LIVE
 0D1 015.7 WL 50
 0D1 020.8 JN 30001 LIVE
 0D1 028.5F1DE 10 RUBBLE
 0D1 028.5 MH 303-30-049
 0D10084 028.5 FH

0H1C33986/AN 303-30-293X 58
 0H2301007 RUE MCTAVISH
 CITY OF MONTREAL
 0H3303-30-292 303-30-293
 0H4CU 900 600EBR 0208Z
 0H50011
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-30-292
 0D1 000.0 WL 10
 0D1 001.4S1DE 05 RUBBLE
 0D1 004.1C1DE 10 BRICKS
 0D1 005.8 CXI 15008 0050
 0D1 005.9 CXI 15008 0050
 0D1 016.9 CX 22502
 0D1 020.8F1DE 10 RUBBLE
 0D1 020.8 MH 303-30-293
 0D10085 020.8 FH

0H1C33986/AN 303-30-294X 59
 a1=MPEG_A_10302007_0124_62_1460i.mp2
 0H23010070122 RUE MCTAVISH
 CITY OF MONTREAL
 0H3303-30-293 303-30-294
 0H4CU 900 600EBR 0033Z
 0H50011
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-30-293
 0D1 000.0 WL 15
 0D1 000.3S1DE 10 RUBBLE
 0D1 003.3C1DE 15 RUBBLE
 0D1 003.3F1DE 15 RUBBLE
 0D10035 003.3 SA DUE TO OVERLAP

0H1C33986/AN R-407 X 60
 0H23010070247 RUE SAINT-JEAN-BAPTISTE
 CITY OF MONTREAL
 0H3R-407 R-408
 0H4CD 900 600EBR 0249Z
 0H50011
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-407
 0D1 000.0 WL 05
 0D1 001.4S1DE 15 STONES
 0D1 003.0 DE 10 BRICKS
 0D1 004.8F1DE 15 STONES
 0D1 009.9 CN 30010
 0D1 010.1 CN 30010
 0D1 010.1 DE 10 BRICKS
 0D1 011.8 CNI 22503 0050LIVE
 0D1 013.1 CN 22509 SEALED
 0D1 013.1 CN 22511 LIVE
 0D1 013.8 CNI 22510 0050
 0D1 015.6 CNI 22510 0050
 0D1 015.6 CNI 22503 0075
 0D1 021.4 CN 30010 SEALED OFF
 0D1 024.6 SA DE 10% CONCRETE
 0D1 024.9 CNI 22510 0050
 0D10124 024.9 DE 10 CONCRETE

0H1C33986/AN R-411 X 61
 0H2301007 RUE SAINT-JEAN-BAPTISTE
 CITY OF MONTREAL
 0H3R-412 R-411
 0H4CU 900 600EBR 0158Z
 0H50011
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-412
 0D1 000.0 WL 05
 0D1 001.4S1DE 25 RUBBLE
 0D1 001.4 CNI 22510 0050
 0D1 001.4S2FL 12
 0D1 002.6 CN 22503
 0D1 015.8F1DE 25 RUBBLE
 0D1 015.8F2FL 12
 0D1 015.8 MH R-411
 0D10042 015.8 FH

0H1C33986/AN R-412 X 62
 0H23010070346 RUE SAINT-JEAN-BAPTISTE
 CITY OF MONTREAL
 0H3R-412 R-MAIN
 0H4CD 900 600EBR 0063Z
 0H50011
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-412
 0D1 000.0 WL 05
 0D1 001.4S1DES 15
 0D1 006.3F1DES 15
 0D1 006.3 MH R-MAIN
 0D10023 006.3 FH

0H1C33986/AN R-409 X 63
 0H23010070412 RUE SAINT-JEAN-BAPTISTE
 CITY OF MONTREAL
 0H3R-409 R-410
 0H4CD 600 CCO 2500062Z
 0H50012
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-409
 0D1 000.0 WL 05
 0D1 003.2 CN 22501
 0D1 004.7 CN 22510
 0D1 004.7 WL 30
 0D1 006.2 MH R-410
 0D10031 006.2 FH

0H1C33986/AN R-408 X 64
 0H23010070432 RUE SAINT-JEAN-BAPTISTE
 CITY OF MONTREAL
 0H3R-409 R-408
 0H4CU 900600 EBR 0362Z
 0H50012
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-409
 0D1 000.0 WL 05
 0D1 001.4 DE 10 RUBBLE
 0D1 001.7 CNI 22511 0025
 0D1 001.7 CX 30001
 0D1 004.7 GO NARROW INVERT
 0D1 004.7 CN 22510 SEALED OFF
 0D1 004.7 CN 22502 SEALED OFF
 0D1 008.5 CN 22510 LIVE
 0D1 016.4 CN 22510 LIVE
 0D1 022.3 CNI 15001 0075LIVE
 0D1 022.3S1EL 0705
 0D1 030.2 CN 22510 SEALED OFF
 0D1 032.9 CN 22510 SEALED OFF
 0D1 035.7S2DE 10 RUBBLE
 0D1 036.2F1EL 0705
 0D1 036.2F2DE 10 RUBBLE
 0D10124 036.2 SA DE 10% RUBBLE

0H1C33986/AN R-408 X 65
 0H23010070451 RUE SAINT-JEAN-BAPTISTE
 CITY OF MONTREAL
 0H3R-408 R-409
 0H4CD 900600 EBR 0000Z
 0H5 UNABLE TO LOCATE R-408
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-408
 0D1 000.0 WL 05
 0D10000 000.0 SA NOT LOCATE R-408

0H1C33986/AN R-407 X 66
 0H23010070454 RUE SAINT-JEAN-BAPTISTE
 CITY OF MONTREAL
 0H3R-408 R-407
 0H4CU 900600 EBR 0000Z
 0H5 UNABLE TO LOCATE R-408
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-408
 0D1 000.0 WL 05
 0D10000 000.0 SA NOT LOCATE R-408

0H1C33986/AN R-147 X 67
 0H20511072250 RUE SAINT-MAURICE
 CITY OF MONTREAL
 0H3R-147 R-146
 0H4CD 750 CCO 2500917Z
 0H50013
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-147
 0D1 000.0 WL 05
 0D1 000.1 GO NOSONAR LOWWATER
 0D1 002.8S1DE 05 RUBBLE
 0D1 004.7 CX 15004
 0D1 007.3F1DE 05 RUBBLE
 0D1 018.0 CX 15002 SEALED OFF
 0D1 030.6 CN 22503 LIVE
 0D1 036.0S2DES 05
 0D1 038.0 CN 22510 LIVE
 0D1 038.0F2DES 05
 0D1 047.7 CN 22503 LIVE
 0D1 060.6 CNI 15001 0050
 0D1 065.6 CN 22510
 0D1 065.6S3DES 05
 0D1 070.1F3DES 05
 0D1 070.1S4DE 10 RUBBLE
 0D1 074.7 CN 15010
 0D1 074.7F4DE 05 RUBBLE
 0D1 081.0S5DE 05 RUBBLE
 0D1 091.7F5DE 05 RUBBLE
 0D1 091.7 MH R-146
 0D10134 091.7 FH

0H1C33986/AN R-146 X 68
 0H20511072307 RUE SAINT-MAURICE
 CITY OF MONTREAL
 0H3R-146 R-145
 0H4CD 750 CCO 2500130Z
 0H50013
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-146
 0D1 000.0 WL 05
 0D1 000.1 GO NOSONAR LOWWATER
 0D1 005.1 CN 22503
 0D1 005.9 CN 22510
 0D1 013.0 MH R-145
 0D10034 013.0 FH

0H1C33986/AN R-147 X 69
 0H20511072317 RUE SAINT-MAURICE
 CITY OF MONTREAL
 0H3R-147 R-148
 0H4CD 750 CCO 2500525Z
 0H50013
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-147
 0D1 000.0 WL 00
 0D1 000.1 GO NOSONAR LOWWATER
 0D1 004.0 CN 15009
 0D1 004.0S1DES 05
 0D1 008.0 CN 22510
 0D1 013.6 CN 15003
 0D1 013.9 CN 22510
 0D1 022.3 CN 22503
 0D1 023.3 DE 10CONCRETE+BRICK
 0D1 023.9 CXI 15011 0050SEALED
 0D1 023.9C1DES 10
 0D1 032.4 CN 15010
 0D1 039.3 DE 10 RUBBLE
 0D1 041.9 CN 25010
 0D1 041.9 WL 20
 0D1 048.6 CX 15010
 0D1 052.5C1DES 45
 0D1 052.5F1DES 45
 0D10124 052.5 SA DES 45%

0H1C33986/AN R-147 X 70
 a1=MPEG_A_11052007_2351_73_1595i.mp2
 0H2051107 RUE SAINT-MAURICE
 CITY OF MONTREAL
 0H3R-148 R-147
 0H4CU 750 CCO 2500172Z
 0H50013
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-148
 0D1 000.0 WL 05
 0D1 000.1 GO NOSONAR LOWWATER
 0D1 001.3S1DES 20
 0D1 001.8 CXI 15002 0025
 0D1 005.0 CX 15003 SEALED OFF
 0D1 005.0C1DES 25
 0D1 013.4 CN 22503
 0D1 013.4C1DES 30
 0D1 015.9 CNI 22502 0050LIVE
 0D1 017.2 CN 15001
 0D1 017.2C1DES 45
 0D1 017.2F1DES 45
 0D10053 017.2 SA DUE TO DES 45%

0H1C33986/AN R-148 X 71
 0H20511070000 RUE SAINT-MAURICE
 CITY OF MONTREAL
 0H3R-148 R-149
 0H4CD 750 CCO 2500398Z
 0H50013
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-148
 0D1 000.0 WL 05
 0D1 000.1 GO NOSONAR LOWWATER
 0D1 001.3S1DES 10
 0D1 003.0 CN 15010
 0D1 019.1 CX 15010 LIVE
 0D1 025.3 CN 22510
 0D1 027.6 CN 22502
 0D1 027.6C1DES 05
 0D1 032.7C1DES 10
 0D1 036.4 CN 15001 BLOCKSTONES
 0D1 036.4 DE 10 SMALL STONES
 0D1 039.8F1DES 10
 0D1 039.8 MH R-149
 0D10073 039.8 FH

0H1C33986/AN R-119 X 72
 0H20611070043 RUE SAINT-MAURICE
 CITY OF MONTREAL
 0H3R-120 R-119
 0H4CU 750 CCO 2500094Z
 0H50013
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-120
 0D1 000.0 WL 05
 0D1 000.1 GO NOSONAR NOWATER
 0D1 001.3S1DES 10
 0D1 007.2 CN 22511 LIVE
 0D1 009.4F1DES 10
 0D1 009.4 MH R-119
 0D10032 009.4 FH

0H1C33986/AN R-120 X 73
 0H20611070051 RUE SAINT-MAURICE
 CITY OF MONTREAL
 0H3R-120 R-121
 0H4CD 750 CCO 2500374Z
 0H50013
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-120
 0D1 000.0 WL 05
 0D1 000.1 GO NOSONAR LOWWATER
 0D1 001.3S1DES 05
 0D1 002.7 CN 22510
 0D1 011.3F1DES 05
 0D1 020.7 CN 22511
 0D1 032.5 DES 10
 0D1 034.9 CN 22510 LIVE
 0D1 035.7 CN 22502 LIVE
 0D1 037.4 MH R-121
 0D10053 037.4 FH

0H1C33986/AN R-121 X 74
 0H20611070100 RUE SAINT-MAURICE
 CITY OF MONTREAL
 0H3R-121 R-122
 0H4CD 750 CCO 2500148Z
 0H50013
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-121
 0D1 000.0 WL 05
 0D1 000.1 GO NOSONAR LOWWATER
 0D1 008.4 WL 25
 0D1 011.2 WL 30
 0D1 011.2S1DES 25
 0D1 014.8F1DES 25
 0D1 014.8 MH R-122
 0D10043 014.8 FH

0H1C33986/AN R-118 X 75
 0H20611070124 RUE SAINT-MAURICE
 CITY OF MONTREAL
 0H3R-119 R-118
 0H4CU 900 600EBR 0049Z
 0H50013
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-119
 0D1 000.0 WL 05
 0D1 000.1 GO NOSONAR NOWATER
 0D1 001.3S1MS 0705
 0D1 002.6 CXI 22508 0075
 0D1 002.6 LR MARGINAL
 0D1 002.6S2DES 10
 0D1 004.9C2DES 15
 0D1 004.9F2DES 05
 0D1 004.9F1MS 0705
 0D10044 004.9 SA DES 15%

0H1C33986/AN R-118 X 76
 a1=MPEG_A_11072007_0206_79_1667i.mp2
 0H20711070158 RUE SAINT-MAURICE
 CITY OF MONTREAL
 0H3R-118 R-119
 0H4CD 900 600EBR 0348Z
 0H50013
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-118
 0D1 000.0 WL 05
 0D1 001.4 LL SLIGHT
 0D1 001.4S1DES 15
 0D1 001.4S2MS 0804
 0D1 034.8F1DES 15
 0D1 034.8F2MS 0804
 0D10042 034.8 SA DUE TO OVERLAP

0H1C33986/AN R-145 X 77
 0H20711070240 RUE DUKE
 CITY OF MONTREAL
 0H3R-159 R-145
 0H4CU 900 CCO 2500780Z
 0H50013 MH NOS WRONG ON DVD
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-159
 0D1 000.0 WL 05
 0D1 001.4 GO NOSONAR LOWWATER
 0D1 001.4S1DE 05 RUBBLE
 0D1 004.9F1DE 05 RUBBLE
 0D1 033.7 CN 22511 LIVE
 0D1 033.7 CN 22501 LIVE
 0D1 055.5 DE 05 RUBBLE
 0D1 065.0 CN 30001
 0D1 065.0S2DE 05 RUBBLE
 0D1 072.6C2DE 10 RUBBLE
 0D1 074.3 CN 15002
 0D1 078.0F2DE 10 RUBBLE
 0D1 078.0 MH R-145
 0D10101 078.0 FH

0H1C33986/AN R-159 X 78
 a1=MPEG_A_11072007_0311_81_1701i.mp2
 0H2071107 RUE DUKE
 CITY OF MONTREAL
 0H3R-159 R-160
 0H4CD 900 CCO 2500839Z
 0H50013 MH NOS WRONG ON DVD
 0H6A1C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-159
 0D1 000.0 WL 05
 0D1 001.4 GO NOSONAR LOWWATER
 0D1 054.7 CN 22501 LIVE
 0D1 054.7 WL 15
 0D1 054.7S1DES 10
 0D1 059.9C1DES 20
 0D1 073.2C1DES 10
 0D1 080.0F1DES 10
 0D1 082.8 CX 15001
 0D1 083.9 MH R-160
 0D10085 083.9 FH

0H1C33986/AN R-160 X 79
 0H20711070328 RUE DUKE
 CITY OF MONTREAL
 0H3R-160 R-161
 0H4CD 900 CCO 2500068Z
 0H50013
 0H6A3C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-160
 0D1 000.0 WL 05
 0D1 006.8 MH R-161
 0D10015 006.8 FH

 0H1C33986/AN R-158 X 80
 0H20711070338 RUE DUKE
 CITY OF MONTREAL
 0H3R-145 R-158
 0H4CU 900 CCO 2500092Z
 0H50013
 0H6A2C AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-145
 0D1 000.0 WL 05
 0D1 004.6 LU SLIGHT
 0D1 009.2 MH R-158
 0D10021 009.2 FH

 0H1C33986/AN R-141 X 81
 a1=MPEG_A_11072007_0349_84_1727i.mp2
 0H20711070349 RUE DUKE
 CITY OF MONTREAL
 0H3R-158 R-141
 0H4CU 900 CCO 2500592Z
 0H50013
 0H6A2C AZ
 0D10000 000.0 ST
 0D1 000.0 MH
 0D1 000.0 WL 05
 0D1 002.9 CN 22511 LIVE
 0D1 002.9 CN 22501 LIVE
 0D1 004.3 CN 15002 LIVE
 0D1 030.2S1DES 10
 0D1 038.2 CL 12
 0D1 038.2C1DES 15
 0D1 046.9 CX 22512 LIVE
 0D1 046.9C1DES 25
 0D1 047.9C1DES 30
 0D1 059.2F1DES 00
 0D1 059.2 MH R-141
 0D10075 059.2 FH

0H1C33986/AN R-142 X 82
 0H20711072225 RUE-NORTE-DAME
 CITY OF MONTREAL
 0H3R-142 R-141
 0H4CD 900 600EBR 0132Z
 0H50014
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-142
 0D1 000.0 WL 05
 0D1 000.1 GO NOSONAR LOWWATER
 0D1 001.4S1DES 15
 0D1 001.4S2MS 0705
 0D1 005.9 CX 22502 SEALED OFF
 0D1 005.9 RF FROM SEALED CX
 0D1 008.7 CX 22510 SEALED OFF
 0D1 013.2 DH 15
 0D1 013.2F1DES 05
 0D1 013.2F2MS 0705
 0D10061 013.2 SA DUE TO DH 15%

 0H1C33986/AN R-143 X 83
 a1=MPEG_A_11072007_2245_86_1757i.mp2
 0H20711072242 RUE-NORTE-DAME
 CITY OF MONTREAL
 0H3R-142 R-143
 0H4CU 900 600EBR 0059Z
 0H50014
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-142
 0D1 000.0 WL 05
 0D1 000.1 GO NOSONAR LOWWATER
 0D1 001.4S1DES 35
 0D1 001.4S2MS 0804
 0D1 002.9 MB 02
 0D1 003.9 CX 22510
 0D1 003.9 DB 1011
 0D1 004.9 CN 15003
 0D1 005.9C1DES 40
 0D1 005.9F1DES 40
 0D1 005.9F2MS 0804
 0D10043 005.9 SA DUE TO DES 40%

0H1C33986/AN R-142 X 84
 0H20711072305 RUE-NORTE-DAME
 CITY OF MONTREAL
 0H3R-143 R-142
 0H4CU 900 600EBR 0042Z
 0H50014
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-143
 0D1 000.0 WL 10
 0D1 000.1 GO NOSONAR LOWWATER
 0D1 001.4S1DES 15
 0D1 001.4S2MS 0804
 0D1 001.4S3EL 0804
 0D1 004.2F3EL 0804
 0D1 004.2 EM 010510
 0D1 004.2F1DES 15
 0D1 004.2F2MS 0804
 0D10041 004.2 SA DUE TO EM 10%

0H1C33986/AN R-143 X 85
 0H20711072316 RUE-NORTE-DAME
 CITY OF MONTREAL
 0H3R-143 R-144
 0H4CD 900 600EBR 0630Z
 0H50014
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-143
 0D1 000.0 WL 10
 0D1 000.1 GO NOSONAR LOWWATER
 0D1 001.4S1DES 15
 0D1 001.4S2MS 0804
 0D1 001.4S3EL 0804
 0D1 002.7 CX 22502 SEALED OFF
 0D1 002.7S4DV 10
 0D1 005.0 CXI 22510 0050LIVE
 0D1 009.3 CXI 22502 0015SEALED
 0D1 014.7 CXI 25002 0015LIVE
 0D1 022.6 CX 22502 SEALED OFF
 0D1 025.3F4DV 10
 0D1 025.3S5DH 05
 0D1 025.3 DB 0105
 0D1 030.1 CNI 30010 0025LIVE
 0D1 035.1 CX 15011 LIVE
 0D1 035.6 DB 0709
 0D1 035.6 MT 0105
 0D1 035.6 CX 22501 LIVE
 0D1 036.7 CNI 30010 0050LIVE
 0D1 041.6S6FL 12
 0D1 043.2 CN 22510 LIVE
 0D1 043.2 MM 0205
 0D1 045.0 CX 22502 LIVE
 0D1 049.1 CX 15001
 0D1 049.1 MB 04
 0D1 055.9 CXI 22510 0050LIVE
 0D1 055.9 CNI 30010 0050LIVE
 0D1 056.5 CNI 15001 0001SEALED
 0D1 056.5F6FL 12
 0D1 059.7 CNI 22511 0025
 0D1 061.9 DB 0105
 0D1 062.8 DB 0709
 0D1 063.0F1DES 15
 0D1 063.0F2MS 0804
 0D1 063.0F3EL 0804
 0D1 063.0F5DH 05
 0D10193 063.0 SA DUE TO DB

0H1C33986/AN R-143 X 86
 a1=MPEG_A_11072007_2359_89_1822i.mp2
 0H2071107 RUE-NORTE-DAME
 CITY OF MONTREAL
 0H3R-144 R-143
 0H4CU 900 600EBR 0195Z
 0H50014
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-144
 0D1 000.0 WL 05
 0D1 000.1 GO NOSONAR LOWWATER
 0D1 001.4 CX 22503
 0D1 001.4S1DES 15
 0D1 001.4S2MS 0804
 0D1 001.6 CXI 22502 0050SEALED
 0D1 003.0 CXI 22502 0075SEALED
 0D1 009.6 DB 0708
 0D1 009.6 CNI 22510 0075SEALED
 0D1 010.2 CNI 22502 0050SEALED
 0D1 013.0 CX 15011
 0D1 013.0 CXI 15001 0050SEALED
 0D1 014.9 BR 900X600
 0D1 018.9 CNI 30002 0050LIVE
 0D1 018.9 RM 25 FROM CNI
 0D1 019.5F1DES 15
 0D1 019.5F2MS 0804
 0D10105 019.5 SA RM 25% FROM CNI

0H1C33986/AN R-144 X 87
 0H20711070018 RUE-NORTE-DAME
 CITY OF MONTREAL
 0H3R-144 RACCORDEM
 0H4CD 900 600EBR 0088Z
 0H50014
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-144
 0D1 000.0 WL 10
 0D1 000.1 GO NOSONAR LOWWATER
 0D1 001.4S1DES 15
 0D1 001.4S2MS 0804
 0D1 002.3 CNI 22510 0050SEALED
 0D1 002.9 CNI 30009 0050LIVE
 0D1 002.9 MB 1101 POSS REPIAR
 0D1 008.0 CXI 30003 0100LIVE
 0D1 008.8F1DES 05
 0D1 008.8F2MS 0804
 0D10053 008.8 SA DUE TO CXI

0H1C33986/AN R-144 X 88
 0H20711070034 RUE-NORTE-DAME
 CITY OF MONTREAL
 0H3RACCORDEM R-144
 0H4CU 900 600EBR 0000Z
 0H5 NO CAMERA ACCESS
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH RACCORDEM
 0D1 000.0 WL 10
 0D10000 000.0 SA NO CAMERA ACCESS

0H1C33986/AN R-115 X 89
 a1=MPEG_A_11082007_0110_92_1859i.mp2
 0H20811070101 RUE-NORTE-DAME
 CITY OF MONTREAL
 0H3R-116 R-115
 0H4CU 900 600EBR 0076Z
 0H500014
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-116
 0D1 000.0 WL 05
 0D1 001.4S1DES 10
 0D1 001.4S2EL 0804
 0D1 001.4S3MS 0705
 0D1 001.6S4DV 10
 0D1 005.9S5FL 12
 0D1 007.3 CX 22503 SEALED OFF
 0D1 007.3C1DES 15
 0D1 007.5F3MS 0705
 0D1 007.6F1DES 15
 0D1 007.6F2EL 0804
 0D1 007.6F4DV 10
 0D1 007.6F5FL 12
 0D10053 007.6 SA DUE TO DES 15%

0H1C33986/AN R-116 X 90
 0H20811070118 RUE-NORTE-DAME
 CITY OF MONTREAL
 0H3R-116 R-117
 0H4CD 900 600EBR 0127Z
 0H500014
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-116
 0D1 000.0 WL 05
 0D1 001.4S1MS 0705
 0D1 001.4S2DES 10
 0D1 002.8 CXI 22511 0050
 0D1 004.8 CX 22502 SEALED OFF
 0D1 004.8S3DV 05
 0D1 005.7S4FL 12
 0D1 005.7C2DES 15
 0D1 008.6 CXI 22511 0050
 0D1 009.4 CX 22502 SEALED OFF
 0D1 011.9 CNI 22503 0050SEALED
 0D1 012.7C2DES 20
 0D1 012.7F1MS 0705
 0D1 012.7F2DES 20
 0D1 012.7F3DV 05
 0D1 012.7F4FL 12
 0D10061 012.7 SA DUE TO DES 20%

0H1C33986/AN R-116 X 91
 0H20811070204 RUE-NORTE-DAME
 CITY OF MONTREAL
 0H3R-117 R-116
 0H4CU 900 600EBR 0000Z
 0H5 NO CAMERA ACCESS
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-117
 0D1 000.0 WL 05
 0D10000 000.0 SA NO CAMERA ACCESS

0H1C33986/AN R-123 X 92
 0H20811070238 DE L, INSPECTEUR
 CITY OF MONTREAL
 0H3R-123 R-122
 0H4CD1200 900EBR 0849Z
 0H500014
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-123
 0D1 000.0 WL 45
 0D1 000.0S1MS 0903
 0D1 001.5S2DES 30
 0D1 001.5S3EL 0903
 0D1 007.3 CX 30002
 0D1 007.3 CXI 22509 0050SEALED
 0D1 010.6 BR 900X600
 0D1 011.9 CN 22510 SEALED OFF
 0D1 012.9 BR 900X600
 0D1 015.9 CN 15011
 0D1 021.6 MB 1011 POSS CX
 0D1 033.8 CX 30010 SEALED OFF
 0D1 039.5 MT 03
 0D1 046.9 CX 30011 SEALED OFF
 0D1 048.9 CN 22503
 0D1 052.3 CX 30010 SEALED OFF
 0D1 054.8 CX 22510
 0D1 054.8 RF
 0D1 057.7 CX 22502 SEALED
 0D1 057.9 CXI 30009 0075SEALED
 0D1 060.8 CX 22503 LIVE
 0D1 064.3 CX 22501 SEALED OFF
 0D1 066.8 CXI 30009 0100SEALED
 0D1 066.8 IG 10
 0D1 068.2 ID 10
 0D1 070.0 IG 02
 0D1 070.0S4DV 10
 0D1 070.0S5FL 12
 0D1 074.1 CX 30003 SEALED OFF
 0D1 074.1 CX 22501 SEALED OFF
 0D1 081.7 CN 15001 SEALED OFF
 0D1 081.7 RF
 0D1 082.5 CX 15011 LIVE
 0D1 083.6 CN 15011 SEALED OFF
 0D1 084.9F1MS 0903
 0D1 084.9F2DES 30
 0D1 084.9F4DV 10
 0D1 084.9F5FL 02
 0D1 084.9F3EL 0903
 0D1 084.9 MH R-122
 0D10325 084.9 FH

0H1C33986/AN R-117 X 93
 a1=MPEG_A_11082007_0334_97_1954i.mp2
 0H20811070329 DE-L, INSPECTEUR
 CITY OF MONTREAL
 0H3R -122 R-117
 0H4CU1200 900EBR 0071Z
 0H500014
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH E-122
 0D1 000.0 WL 20
 0D1 000.1S1MM 0903
 0D1 000.1S2DES 40
 0D1 003.3 CNI 30011 0050SEALED
 0D1 003.3 CN 30002 SEALED OFF
 0D1 007.1C2DES 45
 0D1 007.1F1MM 0903
 0D1 007.1 BR 900X600
 0D1 007.1F2DES 40
 0D10054 007.1 SA DUE TO BRANCH

0H1C33986/AN R-123 X 94
 a1=MPEG_A_11082007_0404_98_1968i.mp2
 0H2081107 DE-L, INSPECTEUR
 CITY OF MONTREAL
 0H3R-123 RACCORDEM
 0H4CD1200 900EBR 0102Z
 0H500014
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-123
 0D1 000.0 WL 40
 0D1 001.4S1MS 0903
 0D1 001.4S2DES 40
 0D1 002.1 MB 11
 0D1 006.6 DB 09
 0D1 006.6 CX 30009
 0D1 006.6S3EL 0903
 0D1 010.2C2DES 45
 0D1 010.2F1MS 0903
 0D1 010.2F2DES 45
 0D1 010.2F3EL 0903
 0D10074 010.2 SA DUE TO DES 45%

0H1C33986/AN R-123 X 95
 0H20811070415 DE-L, INSPECTEUR
 CITY OF MONTREAL
 0H3RACCORDEM R-123
 0H4CU1200 900EBR 0000Z
 0H5 NO CAMERA ACCESS MAIN SEWER
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH RACCORDEM
 0D1 000.0 WL 45
 0D10000 000.0 SA NOACC. MAINSEWER

0H1C33986/AN R-170 X 96
 0H20811070502 RUE-NAZARETH
 CITY OF MONTREAL
 0H3R-171 R-170
 0H4CU 750 CCO 0014Z
 0H500014
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-171
 0D1 000.0 WL 35
 0D1 001.4 DES 30
 0D10010 001.4 SA DUE TO DES 30%

0H1C33986/AN R-171 X 97
 0H20811070510 RUE-NAZARETH
 CITY OF MONTREAL
 0H3R-171 R-173
 0H4CD 750 CCO 2500034Z
 0H500014
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-171
 0D1 000.0 WL 40
 0D1 000.1S1DES 30
 0D1 003.4C1DES 35
 0D1 003.4F1DES 35
 0D10023 003.4 SA DUE TO DES 35%

0H1C33986/AN R-172 X 98
 0H20811070514 RUE-NAZARETH
 CITY OF MONTREAL
 0H3R-171 R-172
 0H4CU 300 CCO 2500001Z
 0H500014
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-171
 0D1 000.0 WL 05
 0D1 000.1 DE 25 RUBBLE
 0D10011 000.1 SA DE 25% RUBBLE

0H1C33986/AN R-156 X 99
 0H20811072228 RUE-SAINT HENRI
 CITY OF MONTREAL
 0H3R-156 RACCORDEM
 0H4CD 600 BBR 0001Z
 0H50014
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-156
 0D1 000.0 WL 00
 0D1 000.1 DES 85
 0D10025 000.1 SA DUE TO DES 85%

0H1C33986/AN R-156 X 100
 a1=MPEG_A_11082007_2238_104_2008i.mp2
 0H20811072238 RUE-SAINT HENRI
 CITY OF MONTREAL
 0H3R-156 R-157
 0H4CD 600 BBR 0001Z
 0H50014
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH
 0D1 000.0 WL 00
 0D1 000.1 DES 85
 0D10015 000.1 SA DUE TO DES 85%

0H1C33986/AN R-156 X 101
 0H20811072304 RUE-SAINT HENRI
 CITY OF MONTREAL
 0H3R-157 R-156
 0H4CU 600 BBR 0322Z
 0H50015
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-157
 0D1 000.0 WL 05
 0D1 001.4S1DES 15
 0D1 001.4S2MM 0804
 0D1 001.4S3DV 10
 0D1 001.4S4DB 1002
 0D1 001.4S5FL 12
 0D1 002.0C1DES 25
 0D1 002.0F5FL 12
 0D1 012.9 MB 1011
 0D1 012.9F1DES 25
 0D1 015.4 DE 05 BRICK
 0D1 019.3S6DE 15 RUBBLE
 0D1 019.8 MB 1202
 0D1 021.4 CX 22509
 0D1 022.7F4DB 1002
 0D1 022.7F6DE 15 RUBBLE
 0D1 022.7S7DES 15
 0D1 024.9 CX 22502 BLOCKED
 0D1 029.4 DB 1101
 0D1 031.4 DB 0809
 0D1 032.2 CXI 30009 0300
 0D1 032.2F2MM 0804
 0D1 032.2F3DV 10
 0D1 032.2F7DES 15
 0D10142 032.2 SA DUE TO CXI

0H1C33986/AN R-157 X 102
 0H20811072329 RUE-SAINT HENRI
 CITY OF MONTREAL
 0H3R-157 RACCORDEM
 0H4CD 600 BBR 0030Z
 0H50015
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-157
 0D1 000.0 WL 05
 0D1 000.0S1MM 0804
 0D1 000.1 MB 0508
 0D1 001.4 LL SLIGHT
 0D1 003.0 MC Vitrified clay
 0D1 003.0 SC CIRCULAR
 0D1 003.0F1MM 0804
 0D1 003.0 DC 300
 0D10071 003.0 SA DUE TO DC

0H1C33986/AN R-157 X 103
 0H20811070004 RUE-SAINT HENRI
 CITY OF MONTREAL
 0H3RACCORDEM R-157
 0H4CU 600 BBR 0000Z
 0H5 NO CAMERA ACCESS
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH RACCORDEM
 0D1 000.0 WL 05
 0D10000 000.0 SA NOACC FROM MAIN

0H1C33986/AN R-153 X 104
 0H20911070008 RUE-SAINT PAUL
 CITY OF MONTREAL
 0H3R-153 R-154
 0H4CD 900 600EBR 0042Z
 0H50015
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-153
 0D1 000.0 WL 10
 0D1 001.4S1DES 20
 0D1 001.4S2MS 0804
 0D1 001.4 CN 15011
 0D1 002.5 CN 22502 SEALED OFF
 0D1 004.2C1DES 25
 0D1 004.2F1DES 25
 0D1 004.2F2MS 0804
 0D1 004.2 SA DUE TO DES 25%

0H1C33986/AN R-152 X 105
 a1=MPEG_A_11092007_0020_109_2072i.mp2
 0H20911070015 RUE-SAINT PAUL
 CITY OF MONTREAL
 0H3R-153 R-152
 0H4CU 900 600EBR 0039Z
 0H50015
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-153
 0D1 000.0 WL 10
 0D1 001.4S1DES 20
 0D1 001.4S2MS 0804
 0D1 001.4 CX 22501 LIVE
 0D1 001.9 CX 22508
 0D1 003.9C1DES 25
 0D1 003.9F1DES 25
 0D1 003.9F2MS 0804
 0D10032 003.9 SA DUE TO DES 25%

0H1C33986/AN R-153 X 106
 0H20911070042 RUE-SAINT PAUL
 CITY OF MONTREAL
 0H3R-154 R-153
 0H4CU 900 600EBR 0706Z
 0H50015
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-154
 0D1 000.0 WL 10
 0D1 001.4S1DES 15
 0D1 001.4S2MS 0804
 0D1 004.7 CN 22504 SEALED OFF
 0D1 004.7 CN 22508 SEALED OFF
 0D1 015.1 CN 22503 SEALED OFF
 0D1 016.0 CN 22502 LIVE
 0D1 016.0C1DES 20
 0D1 022.9S3FL 12
 0D1 022.9S4DV 05
 0D1 026.1 CXI 22504 0100
 0D1 029.1 DB 0103
 0D1 029.8 CN 22510
 0D1 031.4 CX 30002 LIVE
 0D1 031.4 CN 30008 SEALED OFF
 0D1 033.7 CN 15011
 0D1 035.9 CX 22501 LIVE
 0D1 037.5 CNI 22510 0050
 0D1 038.0 CXI 22510 0050LIVE
 0D1 038.0S5EL 0804 CLOCKS VARY
 0D1 041.8 CX 22508
 0D1 043.4F3FL 12
 0D1 043.4F4DV 05
 0D1 045.4 LL SLIGHT
 0D1 050.0 CN 22502
 0D1 052.8 CN 30010
 0D1 054.3 CN 22508 SEALED OFF
 0D1 054.3F5EL 0804 CLOCKS VARY
 0D1 054.3S6EL 1204
 0D1 057.6 CX 30009
 0D1 062.3 CN 15002 LIVE
 0D1 062.3C1DES 00
 0D1 070.0 CX 22510 LIVE
 0D1 070.6S7MB 0711
 0D1 070.6 GOLGVOIDPOSSCOLLAPSE
 0D1 070.6 DE 30 RUBBLE BRICKS
 0D1 070.6F1DES 30
 0D1 070.6F2MS 0804
 0D1 070.6F6EL 1204
 0D1 070.6F7MB 0711
 0D10273 070.6 SA LGVOID COLLAPSING

0H1C33986/AN R-152 X 107
 0H20911070136 RUE-SAINT PAUL
 CITY OF MONTREAL
 0H3 R-152 R-153
 0H4CD 900 600EBR 0226Z
 0H50015
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-152
 0D1 000.0 WL 10
 0D1 000.0 DES 30 10.6
 0D1 001.4S1MS 0804
 0D1 001.4S2DES 25
 0D1 001.4 CX 15010
 0D1 004.3 CN 22511 LIVE
 0D1 008.6 CXI 22501 0050SEALED
 0D1 009.8 CXI 30009 0075SEALED
 0D1 010.6S3EL 0804 CLOCKS VARY
 0D1 010.6C2DES 30
 0D1 018.6 WL 45
 0D1 018.6 CX 30002
 0D1 022.6 MB 1205
 0D1 022.6 GO LGVOID COLLPSING
 0D1 022.6F1MS 0804
 0D1 022.6F2DES 30
 0D1 022.6F3EL 0804 CLOCKS VARY
 0D10140 022.6 DE 40 FROM COLLAPSE

0H1C33986/AN R-151 X 109
 0H20911070226 RUE-SAINT PAUL
 CITY OF MONTREAL
 0H3R-151 R-152
 0H4CD 900 600EBR 0081Z
 0H50015
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-151
 0D1 000.0 WL 05
 0D1 001.4S1DES 25
 0D1 001.4S2MS 0804
 0D1 002.0 CN 22501
 0D1 003.1 MB 10
 0D1 003.2 CXI 22502 0050
 0D1 005.4S3LL SLIGHT
 0D1 008.1C1DES 30
 0D1 008.1F1DES 30
 0D1 008.1F2MS 0804
 0D1 008.1F3LL SLIGHT
 0D10042 008.1 SA DUE TO DES 30%

0H1C33986/AN R-151 X 108
 0H20911070200 RUE-SAINT PAUL
 CITY OF MONTREAL
 0H3R-152 R-151
 0H4CU 900 600EBR 0036Z
 0H50015
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-152
 0D1 000.0 WL 15
 0D1 001.4S1MS 0804
 0D1 001.4S2DES 25
 0D1 002.3 CN 22510 SEALED OFF
 0D1 003.6C2DES 30
 0D1 003.6F1MS 0804
 0D1 003.6F2DES 30
 0D10035 003.6 SA DUE TO DES 30%

0H1C33986/AN R-150 X 110
 0H20911070237 RUE-SAINT PAUL
 CITY OF MONTREAL
 0H3R-151 R-150
 0H4CU 900 600EBR 0401Z
 0H50015
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-151
 0D1 000.0 WL 05
 0D1 001.4S1DES 25
 0D1 001.4S2MS 0804
 0D1 001.4S3LL SLIGHT
 0D1 001.4 CN 22510 SEALED OFF
 0D1 004.9 CXI 15011 0150
 0D1 006.9S4EL 0804
 0D1 006.9F3LL SLIGHT
 0D1 013.9 CNI 30001 0025LIVE
 0D1 013.9C1DES 35
 0D1 015.1 CN 22508 LIVE
 0D1 015.9 CXI 22502 0050SEALED
 0D1 016.9 CXI 30002 0050SEALED
 0D1 017.9 CNI 22502 0050
 0D1 021.3 CNI 22503 050BLOCKED
 0D1 022.5 CNI 30009 0050SEALED
 0D1 025.6 CXI 22502 0050
 0D1 028.1 CNI 22510 0050
 0D1 028.1 RF
 0D1 028.9 CX 22503 SEALED OFF
 0D1 030.6 CX 15001 LIVE
 0D1 034.0 GO POSS OLD MH SHAFT
 0D1 037.9 MB 1202
 0D1 038.5 CN 60002
 0D1 039.9 CNI 15009 0050LIVE
 0D1 040.0C1DES 45
 0D1 040.0F1DES 40
 0D1 040.0F2MS 0804
 0D1 040.0F4EL 0804
 0D10212 040.0 SA DUE TO DES 40%

0H1C33986/AN R-150 X 111
 0H20911070325 RUE-SAINT PAUL
 CITY OF MONTREAL
 0H3R-150 R-151
 0H4CD 900 600EBR 0026Z
 0H50015
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-150
 0D1 000.0 WL 10
 0D1 001.4S1DES 30
 0D1 001.4S2MS 0804
 0D1 001.4 CN 22503 SEALED OFF
 0D1 001.4 CN 22509 SEALED OFF
 0D1 002.6C1DES 40
 0D1 002.6F1DES 40
 0D1 002.6F2MS 0804
 0D10030 002.6 SA DUE TO DES 40%

0H1C33986/AN R-155 X 112
 0H20911070441 RUE-SAINT-HENRI
 CITY OF MONTREAL
 0H3R-155 RACCORDEM
 0H4CD 900 600EBR 0171Z
 0H50015
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-155
 0D1 000.0 WL 05
 0D1 001.4S1DES 10
 0D1 001.4S2MS 0705
 0D1 013.3F1DES 10
 0D1 013.3S3LD SLIGHT
 0D1 017.1F2MS 0705
 0D1 017.1F3LD
 0D10044 017.1 SA CAM STUCK IN INVT

0H1C33986/AN R-155 X 113
 0H20911070509 RUE-SAINT-HENRI
 CITY OF MONTREAL
 0H3R-155 R-155A
 0H4CD 900 600EBR 0091Z
 0H50015
 0H6A2B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-155
 0D1 000.0 WL 00
 0D1 001.4S1DES 10
 0D1 001.4S2MS 0705
 0D1 007.1 CX 22501 SEALED OFF
 0D1 009.1 GO NARROW INVERT
 0D1 009.1F1DES 10
 0D1 009.1F2MS 0705
 0D10059 091.0 SACAMSTUCKNARROWINVT

0H1C33986/AN 303-40-239X 114
 a1=MPEG_A_11092007_2147_118_2239i.mp2
 0H20911072146 RUE-GAUVIN
 CITY OF MONTREAL
 0H3303-40-239 RACCORDEM
 0H4CD 900 600EBR 0585Z
 0H50015
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-40-239
 0D1 000.0 WL 05
 0D1 001.4S1DES 05
 0D1 001.4S2MS 0705
 0D1 027.9C1DES 10
 0D1 039.8S3FL 12
 0D1 039.8S4DV 05
 0D1 039.8F1DES 10
 0D1 039.8S5MT 12
 0D1 049.4F3FL 02
 0D1 049.4F4DV 05
 0D1 049.4F5MT 12
 0D1 056.0S6DES 15
 0D1 058.5 MB 1203
 0D1 058.5 DES 60 FROM MB
 0D1 058.5 DE 10 ROD
 0D1 058.5F2MS 0705
 0D1 058.5F6DES 15
 0D1 058.5 DES 65
 0D10155 058.5 SA DUE TO DES 65%

0H1C33986/AN 303-40-239X 115
 0H20911072209 RUE-GAUVIN
 CITY OF MONTREAL
 0H3RACCORDEM 303-40-239
 0H4CU 900 600EBR 0000Z
 0H5 NO ACCESS FROM MAIN SEWER
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH RACCORDEM
 0D1 000.0 WL 05
 0D10000 000.0 SA NOACC MAIN SEWER

0H1C33986/AN R-136 X 116
 0H20911072249 RUE-PRINCE
 CITY OF MONTREAL
 0H3R-136 R-137
 0H4CD 900 CPP 0345Z
 0H500016 FINISH MH NO WRONG ON DVD
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-136
 0D1 000.0 WL 05
 0D1 001.3S1DV 05
 0D1 001.4S2FL 12
 0D1 001.4 SC EGG
 0D1 001.4 DC 900900X600
 0D1 001.4 MC Brick
 0D1 001.4S3DES 25
 0D1 001.4S4EL 0804
 0D1 001.4S5MS 0804
 0D1 007.1 CN 22510
 0D1 018.2 CNI 30003 0050
 0D1 018.2F2FL 12
 0D1 018.2F1DV 05
 0D1 021.1 CNI 30003 0050
 0D1 023.1 CNI 30003 0050
 0D1 023.1 WL 25
 0D1 029.2S6FL 02
 0D1 031.3 CNI 30009 0025
 0D1 033.4 CNI 30003 0050SEALED
 0D1 034.5C3DES 30
 0D1 034.5F3DES 00
 0D1 034.5F4EL 0804
 0D1 034.5F5MS 0804
 0D1 034.5F6FL 12
 0D10173 034.5 SA DUE TO DES 30%

0H1C33986/AN R-128 X 117
 0H20911072355 RUE-DALHOUSIE
 CITY OF MONTREAL
 0H3R-129 R-128
 0H4CU 900 600EBR 0039Z
 0H500016 FINISH MH NO WRONG ON DVD
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-129
 0D1 000.0 WL 05
 0D1 001.4S1MS 0804
 0D1 001.4S2DES 35
 0D1 001.4S3FL 12
 0D1 001.4S4DV 05
 0D1 002.5 CX 30008 SEALED OFF
 0D1 002.9 CNI 22511 0050
 0D1 003.3 CN 22502
 0D1 003.9F1MS 0804
 0D1 003.9F2DES 35
 0D1 003.9F3FL 12
 0D1 003.9F4DV 05
 0D10043 003.9 SA DUE TO DES 35%

OH1C33986/AN R-129 X 118
 OH2091107 RUE-DALHOUSIE
 CITY OF MONTREAL
 OH3R-129 R-130
 OH4CD 900 600EBR 0016Z
 OH500016
 OH6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-129
 OD1 000.0 WL 05
 OD1 001.4S1DES 30
 OD1 001.4S2MS 0804
 OD1 001.4S3FL 12
 OD1 001.4S4DV 05
 OD1 001.4 CXI 30002 0050
 OD1 001.6C1DES 35
 OD1 001.6F1DES 35
 OD1 001.6F2MS 0804
 OD1 001.6F3FL 12
 OD1 001.6F4DV 05
 OD10025 001.6 SA DUE TO DES 35%

OH1C33986/AN R-129 X 122
 OH2091107 RUE-DALHOUSIE
 CITY OF MONTREAL
 OH3R-130 R-129
 OH4CU 900 600EBR 0134Z
 OH500016
 OH6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-130
 OD1 000.0 WL 05
 OD1 001.4S1DES 05
 OD1 001.4S2MS 0705
 OD1 001.4S3EL 0804
 OD1 010.3 CXI 22510 0050LIVE
 OD1 010.3 CNI 22503 050SEALED
 OD1 012.2 CXI 22509 0050SEALED
 OD1 013.4C1DES 15
 OD1 013.4F1DES 15
 OD1 013.4F2MS 0804
 OD1 013.4F3EL 0804
 OD10053 013.4 SA DUE TO DES 15%

OH1C33986/AN R-128 X 119
 OH20911070014 RUE-DALHOUSIE
 CITY OF MONTREAL
 OH3R-128 R-129
 OH4CD 900 600EBR 0000Z
 OH5 DUE TO PARKED CAR ON R-128
 OH6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-128
 OD1 000.0 WL 05
 OD10000 000.0 SA PARKEDCARON R-128

OH1C33986/AN R-130 X 123
 OH21011070052 RUE-DALHOUSIE
 CITY OF MONTREAL
 OH3R-130 R-131
 OH4CD 900 600EBR 0163Z
 OH500016
 OH6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-130
 OD1 000.0 WL 05
 OD1 001.4S1DES 10
 OD1 001.4S2MS 0804
 OD1 001.4S3EL 0804
 OD1 003.5S4LR SLIGHT
 OD1 008.5 CN 22510
 OD1 012.1F4LR SLIGHT
 OD1 016.3F1DES 10
 OD1 016.3F2MS 0804
 OD1 016.3F3EL 0804
 OD1 016.3 MH R-131
 OD10085 016.3 FH

OH1C33986/AN R-127 X 120
 OH20911070016 RUE-DALHOUSIE
 CITY OF MONTREAL
 OH3R-128 R-127
 OH4CU 900 600EBR 0000Z
 OH5 PARKED CARS
 OH6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-128
 OD1 000.0 WL 05
 OD10000 000.0 SA PARKEDCARSONR-128

OH1C33986/AN R-127 X 121
 OH20911070018 RUE-DALHOUSIE
 CITY OF MONTREAL
 OH3R-127 R-128
 OH4CD 900 600EBR 0000Z
 OH5 R-127 PARKED CAR
 OH6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-127
 OD1 000.0 WL 05
 OD10000 000.0 SA PARKEDCARONR-127

OH1C33986/AN R-132 X 124
 OH21011070209 RUE-OTTAWA
 CITY OF MONTREAL
 OH3R-132 MUR
 OH4CD 900 600EBR 0289Z
 OH500016
 OH6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-132
 OD1 000.0 WL 05
 OD1 001.4S1DES 15
 OD1 001.4S2MS 0804
 OD1 001.4S3EL 0804
 OD1 002.5 CXI 30002 0050
 OD1 021.3F1DES 15
 OD1 021.3 CN 22501
 OD1 021.3 CN 22511 LIVE
 OD1 022.5 MB 03
 OD1 028.9F2MS 0804
 OD1 028.9F3EL 0804
 OD1 028.9 MH MUR
 OD10062 028.9 FH

OH1C33986/AN R-132 X 125
 OH21011070228 RUE-OTTAWA
 CITY OF MONTREAL
 OH3R-132 R-133
 OH4CD 900 600EBR 0312Z
 OH500016
 OH6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-132
 OD1 000.0 WL 05
 OD1 001.4S1DES 25
 OD1 001.4S2MS 0804
 OD1 001.4S3FL 12
 OD1 001.5S4DV 05
 OD1 005.9F3FL 12
 OD1 005.9F4DV 05
 OD1 024.9 CX 22501
 OD1 029.7 CX 22502
 OD1 030.5 CXI 30010 0050LIVE
 OD1 031.1 MB 1101
 OD1 031.1 CXI 22503 0075
 OD1 031.1 CXI 22509 0075
 OD1 031.1 DC 450
 OD1 031.1F1DES 25
 OD1 031.1F2MS 0804
 OD10091 031.1 SA DES 45% AND DC
 OD1 031.2 DES 45

OH1C33986/AN R-133 X 126
 a1=MPEG_A_11102007_0308_130_2403i.mp2
 OH2101107 RUE-OTTAWA
 CITY OF MONTREAL
 OH3R-133 R-134
 OH4CD 900 600EBR 0345Z
 OH500016
 OH6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-133
 OD1 000.0 WL 05
 OD1 001.4S1MS 0705
 OD1 001.4 CNI 15010 0075
 OD1 001.4S2EL 0205
 OD1 006.3 CX 22511 SEALED OFF
 OD1 006.3 CX 22501 SEALED OFF
 OD1 006.3S3DE 10 RUBBLE
 OD1 008.5 CN 22510
 OD1 015.5 CXI 22511 0050SEALED
 OD1 017.5 CXI 22511 0050SEALED
 OD1 026.3 CX 22510 SEALED OFF
 OD1 029.0S4FL 12
 OD1 029.0S5MT 12
 OD1 029.0S6DV 05
 OD1 029.0 CXI 22502 0050
 OD1 029.9 CNI 22511 0050
 OD1 034.5F1MS 0705
 OD1 034.5F3DE 10
 OD1 034.5F2EL 0205
 OD1 034.5F4FL 12
 OD1 034.5F5MT 12
 OD1 034.5F6DV 05
 OD1 034.5 MH R-134
 OD10110 034.5 FH

OH1C33986/AN R-134 X 127
 OH21011070324RUE-OTTAWA
 CITY OF MONTREAL
 OH3R-134 R-135
 OH4CD 900 600EBR 0002Z
 OH500016
 OH6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-134
 OD1 000.0 WL 00
 OD1 000.2 DES 40
 OD1 000.2 MS 0804
 OD10014 000.2 SA DUE TO DES 40%

0H1C33986/AN R-132 X 128
 0H21011070329RUE-OTTAWA
 CITY OF MONTREAL
 0H3R-133 R-132
 0H4CU 900 600EBR 0000Z
 0H5 NO CAMERA ACCESS
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-133
 0D1 000.0 WL 05
 0D10000 000.0 SA NO CAMERA ACCESS

0H1C33986/AN R-176 X 129
 0H21011070338 RUE-NAZERETH
 CITY OF MONTREAL
 0H3R-133 R-176
 0H4CU 900 600EBR 0079Z
 0H500016
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-133
 0D1 000.0 WL 10
 0D1 001.4S1MS 0804
 0D1 001.4S2DES 30
 0D1 004.5 CN 22501
 0D1 004.5 CX 15011
 0D1 005.8C2DES 40
 0D1 007.9 CX 30002
 0D1 007.9 DB 0204
 0D1 007.9F1MS 0804
 0D1 007.9F2DES 40
 0D10065 007.9 SA DUE TO DES 40%

0H1C33986/AN R-133 X 130
 0H21011070348 RUE-NAZERETH
 CITY OF MONTREAL
 0H3R-133 R-177
 0H4CD 900 600EBR 0034Z
 0H500016
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-133
 0D1 000.0 WL 15
 0D1 001.4S1MS 0804
 0D1 001.4S2DES 30
 0D1 003.3C2DES 35
 0D1 003.3F1MS 0804
 0D1 003.3F2DES 35
 0D10025 003.4 SA DUE TO DES 35%

0H1C33986/AN R-155 X 131
 0H21011070423 RUE-HENRI
 CITY OF MONTREAL
 0H3R-155A R-155
 0H4CU 900 600EBR 0408Z
 0H500017
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-155A
 0D1 000.0 WL 05
 0D1 001.4S1MS 07
 0D1 015.4S2DES 05
 0D1 027.3 CX 22511
 0D1 027.3F2DES 05
 0D1 027.3S3DE 10 RUBBLE
 0D1 029.0 CX 15011
 0D1 029.4 CX 15011
 0D1 034.3 CX 15011
 0D1 036.0 LL SLIGHT
 0D1 038.7 LR SLIGHT
 0D1 040.6 DE 10 BRICK
 0D1 040.8F1MS 0705
 0D1 040.8F3DE 00 RUBBLE
 0D10104 040.8 SA DE 10% BRICK

0H1C33986/AN R-155A X 132
 0H21011070441 RUE-HENRI
 CITY OF MONTREAL
 0H3R-155A R-148
 0H4CD 600 CCO 2500150Z
 0H500016
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-155A
 0D1 000.0 WL 05
 0D1 001.4S1DE 10 CONCRETE
 0D1 002.0 CX 22511 SEALED OFF
 0D1 005.2 CX 22511
 0D1 006.9 JN 15011
 0D1 006.9F1DE 10 CONCRETE
 0D1 015.0 MH R-148
 0D10052 015.0 FH

0H1C33986/AN R-164 X 133
 a1=MPEG_A_11102007_2152_137_2493i.mp2
 0H21011072118 RUE-DUKE
 CITY OF MONTREAL
 0H3R-164 R-163
 0H4CD 900 EBR 0568Z
 0H500017
 0H6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-164
 OD1 000.0 WL 05
 OD1 001.4S1MS 0804
 OD1 001.4S2DES 25
 OD1 001.4 CNI 15009 0075
 OD1 006.9 CNI 22509 0050
 OD1 020.5 CN 22503
 OD1 023.0 CN 15009 SEALED OFF
 OD1 027.5 CNI 22502 0050LIVE
 OD1 027.5 V
 OD1 032.2 CX 22510 SEALED OFF
 OD1 033.4 CN 22503
 OD1 034.8S3FL 12
 OD1 034.8 CN 22503
 OD1 034.8S4DV 05
 OD1 036.4 CN 22510
 OD1 036.4 DE 30 RUBBLE
 OD1 042.4F3FL 12
 OD1 042.4F4DV 05
 OD1 047.3 CN 22503 SEALED OFF
 OD1 047.7 CX 15011
 OD1 050.1 CN 22501 SEALED OFF
 OD1 050.1 CN 15011
 OD1 051.9 CN 22502 BLOCKED
 OD1 056.8 CN 22511
 OD1 056.8F1MS 0804
 OD1 056.8F2DES 25
 OD1 056.8 DES 30
 OD10193 056.8 SA DUE TO DES 30%

0H1C33986/AN R-164 X 134
 0H21011072231 RUE-DUKE
 CITY OF MONTREAL
 0H3R-163 R-164
 0H4CU 900 EBR 0198Z
 0H500017
 0H6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-163
 OD1 000.0 WL 10
 OD1 001.4S1MS 0804
 OD1 001.4S2DES 20
 OD1 001.4S3EL 0804
 OD1 003.3 CNI 15009 0050
 OD1 007.8 CX 22503 SEALED OFF
 OD1 008.7 CXI 15011 0075SEALED
 OD1 015.5 CN 22511 LIVE
 OD1 017.1 CN 22501
 OD1 017.8 CX 22511
 OD1 017.8 CXI 15011 0075SEALED
 OD1 019.2 CNI 22502 0025
 OD1 019.2C2DES 25
 OD1 019.8F1MS 0804
 OD1 019.8C2DES 25
 OD1 019.8F2DES 25
 OD1 019.8F3EL 0804
 OD10095 019.8 SA DUE TO DES 25%

0H1C33986/AN R-163 X 135
 0H21011072244 RUE-DUKE
 CITY OF MONTREAL
 0H3R-163 R-162
 0H4CD 900 EBR 0059Z
 0H500017
 0H6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-163
 OD1 000.0 WL 10
 OD1 001.4S1MS 0804
 OD1 001.4S2DES 15
 OD1 001.4S3FL 12
 OD1 004.0 CXI 22503 0025SEALED
 OD1 005.2 CN 22502 LIVE
 OD1 005.2 DE 10 CONCRETE
 OD1 005.9F1MS 0804
 OD1 005.9F2DES 15
 OD1 005.9F3FL 02
 OD10073 005.9 SA DE 10% CONCRETE

0H1C33986/AN R-163 X 136
 a1=MPEG_A_11102007_2318_140_2563i.mp2
 0H2101107 RUE-DUKE
 CITY OF MONTREAL
 0H3R-162 R-163
 0H4CU 900 EBR 0932Z
 0H500017
 0H6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-162
 OD1 000.0 WL 05
 OD1 001.4S1MS 0804
 OD1 001.4S2DES 15
 OD1 001.4S3EL 0804
 OD1 003.2 CNI 22501 0050LIVE
 OD1 006.9S4FL 12
 OD1 006.9S5DV 05
 OD1 008.1 CX 15011
 OD1 011.5 CN 22503 SEALED OFF
 OD1 011.6 CX 30010 LIVE
 OD1 012.5 CN 15011
 OD1 012.5F4FL 12
 OD1 012.5F5DV 05
 OD1 016.3 CN 22509
 OD1 027.0 CN 22502 SEALED OFF
 OD1 030.1 CN 22510 SEALED OFF
 OD1 031.4 CN 15011 LIVE
 OD1 031.4S6MM 12
 OD1 037.0 CN 15011
 OD1 038.9 CN 22510
 OD1 039.6 CN 22501
 OD1 042.0 CNI 22511 0075
 OD1 044.2 CN 15010
 OD1 044.6 CN 15010
 OD1 044.6F6MM 12
 OD1 048.5S7FL 12
 OD1 048.5S8DV 05
 OD1 049.1 CNI 30010 0050LIVE
 OD1 049.1 CNI 22501 0025
 OD1 053.2 MB 1202 POSS REPIAR
 OD1 053.2C2DES 30
 OD1 056.2 CXI 22511 0050LIVE
 OD1 056.2 CX 22502
 OD1 058.7F7FL 12
 OD1 058.7F8DV 05
 OD1 065.4S9FL 02
 OD1 065.4SADV 05
 OD1 066.9 CN 15003
 OD1 066.9 CNI 22510 0050
 OD1 068.9 CN 22510
 OD1 072.8F9FL 12
 OD1 072.8FADV 05
 OD1 077.5SBFL 12
 OD1 077.5SCDV 05
 OD1 078.8 CXI 15002 0050SEALED
 OD1 079.0 CNI 15003 0050SEALED
 OD1 079.0C2DES 30

OD1 081.3 CX 22501
 OD1 083.7FBFL 12
 OD1 083.7FCDV 05
 OD1 088.9 CNI 22509 0025
 OD1 093.2 CNI 22510 0050LIVE
 OD1 093.2 DE 10 CONCRETE
 OD1 093.2F1MS 0804
 OD1 093.2F2DES 30
 OD1 093.2F3EL 0804
 OD10324 093.2 SA DUE TO OVERLAP

0H1C33986/AN R-162 X 137
 0H2101107 RUE-DUKE
 CITY OF MONTREAL
 0H3R-162 RACCORDEM
 0H4CD 900 EBR 0529Z
 0H500017
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-162
 0D1 000.0 WL 05
 0D1 000.0F4FL 12
 0D1 001.4S1MS 0804
 0D1 001.4S2DES 15
 0D1 001.4S3EL 0804
 0D1 004.3 CN 22501
 0D1 004.3 IR 01
 0D1 005.8 CX 22511 SEALED OFF
 0D1 010.1 CN 22511 SEALED OFF
 0D1 011.6 CNI 15011 0050
 0D1 011.6 CN 15001
 0D1 013.9 CN 22510 SEALED OFF
 0D1 013.9S4FL 12
 0D1 013.9S5DV 10
 0D1 013.9C2DES 25
 0D1 021.8 CN 22502
 0D1 023.9 CN 22502
 0D1 026.8 CX 30009 SEALED OFF
 0D1 029.5 CX 15010 LIVE
 0D1 031.6 CNI 15003 0100LIVE
 0D1 032.0 CX 22502 SEALEDLIVE
 0D1 035.6 CNI 22503 0025LIVE
 0D1 035.6F5DV 10
 0D1 035.6F3EL 0804
 0D1 035.6S6EM 080410
 0D1 035.6F4FL 02
 0D1 036.9 CX 22511 LIVE
 0D1 037.8 CNI 22511 0025
 0D1 039.4S7FL 12
 0D1 039.4S8DV 05
 0D1 041.9 CX 22510
 0D1 041.9C2DES 35
 0D1 052.9C2DES 40
 0D1 052.9F1MS 0804
 0D1 052.9F2DES 15
 0D1 052.9F7FL 12
 0D1 052.9F6EM 080410
 0D1 052.9F8DV 05
 0D10175 052.9 SA DUE TO DES 40%

0H1C33986/AN R-162 X 138
 0H21011070032 RUE-DUKE
 CITY OF MONTREAL
 0H3RACCORDEM R-162
 0H4CU 900 EBR 0000Z
 0H5 NO CAMERA ACCESS FROM MAIN
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH RACCORDEM
 0D1 000.0 WL 05
 0D10000 000.0 SA NOACCFROM MNSEWER

 0H1C33986/AN R-178 X 139
 a1=MPEG_A_11112007_0142_143_2670i.mp2
 0H21011070126 RUE-NAZARETH
 CITY OF MONTREAL
 0H3R-178 RACCORDEM
 0H4CD 900 EBR 0105Z
 0H500017
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-178
 0D1 000.0 WL 05
 0D1 001.4S1MS 0705
 0D1 002.4 CX 22511 SEALED OFF
 0D1 002.4 CNI 22501 0050
 0D1 002.4S2LR SLIGHT
 0D1 008.3F2LR SLIGHT
 0D1 010.5F1MS 0804
 0D1 010.5 MH RACCORDEM
 0D10040 010.5 FH

0H1C33986/AN R-177 X 140
 0H21011070150 RUE-NAZARETH
 CITY OF MONTREAL
 0H3R-178 R-177
 0H4CU 900 EBR 0337Z
 0H500017
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-178
 0D1 000.0 WL 05
 0D1 001.4S1MS 0705
 0D10000 001.4S2EL 0705
 0D1 002.5 CN 22501 LIVE
 0D1 004.7 CX 15011
 0D1 004.7 EM 091110
 0D1 006.8 CNI 22511 0050LIVE
 0D1 011.7 CNI 15001 0050LIVE
 0D1 015.5S3DES 10
 0D1 027.7 DE 10 RUBBLE
 0D1 032.9 CXI 22501 0050
 0D1 032.9 EM 010510
 0D1 033.7 EH 071130
 0D1 033.7F1MS 0705
 0D1 033.7F2EL 0705
 0D1 033.7F3DES 10
 0D10094 033.7 SA DUE TO EH 30%

0H1C33986/AN R-177 X 141
 a1=MPEG_A_11112007_0243_145_2702i.mp2
 0H2101107 RUE-NAZARETH
 CITY OF MONTREAL
 0H3R-177 R-178
 0H4CD 900 EBR 0014Z
 0H500017
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-177
 0D1 000.0 WL 10
 0D1 001.4 DES 30
 0D10010 001.4 SA DUE TO DES 30%

0H1C33986/AN R-133- X 142
 0H21011070246 RUE-NAZARETH
 CITY OF MONTREAL
 0H3R-177 R-133-
 0H4CU 900 EBR 0014Z
 0H500017
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-177
 0D1 000.0 WL 35
 0D1 001.4 DES 40
 0D10010 001.4 SA DUE TO DES 45%

0H1C33986/AN R-176 X 143
 0H21011070307 RUE-NAZARETH
 CITY OF MONTREAL
 0H3R-176 R-133
 0H4CD 900 EBR 0834Z
 0H500017
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-176
 0D1 000.0 WL 10
 0D1 001.4S1MS 0804
 0D1 001.4S2DES 40
 0D1 003.8 CXI 22511 0075
 0D1 025.8 CX 30003
 0D1 031.7 CX 22502 SEALED OFF
 0D1 032.4 CX 30010
 0D1 035.9 CN 22508
 0D1 037.1 CX 22510
 0D1 038.1 CX 22502
 0D1 039.0 CN 22511
 0D1 039.0C2DES 30
 0D1 053.6 CX 22502 BLOCKED
 0D1 059.9 CN 15011
 0D1 067.8 CX 22502
 0D1 074.4 CN 22502
 0D1 075.1 CX 22510
 0D1 078.9 MB 01
 0D1 078.9 CN 22510 BLOCKED
 0D1 083.4F1MS 0804
 0D1 083.4F2DES 30
 0D1 083.4 MH R-133
 0D10163 083.4 FH

0H1C33986/AN R-175 X 144
 0H21011070334 RUE-NAZARETH
 CITY OF MONTREAL
 0H3R-176 R-175
 0H4CU 900 EBR 0668Z
 0H500017
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-176
 0D1 000.0 WL 10
 0D1 001.4S1MS 0804
 0D1 001.4S2DES 35
 0D1 005.1 CX 22510 SEALED OFF
 0D1 005.8 CN 22503 BLOCKED
 0D1 013.9 CNI 25010 0050
 0D1 015.8 CX 22510 SEALED OFF
 0D1 015.8 CX 15001
 0D1 029.6 CX 22510 SEALED OFF
 0D1 032.0 CX 20001
 0D1 034.4 CX 22510 SEALED OFF
 0D1 056.2 CX 22510 SEALED OFF
 0D1 063.4 CX 15010
 0D1 064.3 CN 15001
 0D1 066.8F1MS 0804
 0D1 066.8F2DES 35
 0D1 066.8 MH R-175
 0D10095 066.8 FH

0H1C33986/AN R-174 X 145
 0H21011070352 RUE-NAZARETH
 CITY OF MONTREAL
 0H3R-175 R-174
 0H4CU 900 EBR 0104Z
 0H500017
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-175
 0D1 000.0 WL 10
 0D1 000.1S1MS 0804
 0D1 000.1S2DES 35
 0D1 001.5 CN 22511
 0D1 002.9 CX 22501
 0D1 004.7 CX 30003 SEALED OFF
 0D1 005.9 CX 22509
 0D1 005.9S3LR MARGINAL
 0D1 008.3 CN 22509
 0D1 010.4F1MS 0804
 0D1 010.4F2DES 35
 0D1 010.4F3LR MARGINAL
 0D1 010.4 MH R-174
 0D10064 010.4 FH

0H1C33986/AN R-201 X 146
 0H21011070447 RUE-WELLINGTON
 CITY OF MONTREAL
 0H3R-174 R-201
 0H4CU 900 EBR 0423Z
 0H500018
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-174
 0D1 000.0 WL 10
 0D1 001.4S1MS 0804
 0D1 001.4S2DES 35
 0D1 002.6S3LR SLIGHT
 0D1 006.5F3LR SLIGHT
 0D1 009.3 CX 30003
 0D1 012.5S4LR SLIGHT
 0D1 015.3F4LR SLIGHT
 0D1 037.8 CN 30003 BLOCKED
 0D1 040.2 CN 30003 LIVE
 0D1 042.3C2DES 00
 0D1 042.3F1MS 0804
 0D1 042.3F2DES 40
 0D10113 042.3 SA DUE TO DES 40%

0H1C33986/AN R-201 X 147
 a1=MPEG_A_11112007_0523_151_2790i.mp2
 0H21011070503 RUE WELLINGTON
 CITY OF MONTREAL
 0H3R-201 R-174
 0H4CD 900 EBR 0245Z
 0H500018
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-174
 0D1 000.0 WL 05
 0D1 001.4S1MS 0804
 0D1 001.4S2DES 30
 0D1 004.8 CX 22503
 0D1 007.2 CX 22509 BLOCKED
 0D1 007.7 CX 15011 LIVE
 0D1 007.7 DB 11
 0D1 019.0 CN 15011
 0D1 024.5F1MS 0804
 0D1 024.5F2DES 30
 0D10045 024.5 SA DUE TO OVERLAP

0H1C33986/AN R-181 X 148
 0H21011070531 RUE WELLINGTON
 CITY OF MONTREAL
 0H3R-201 R-181
 0H4CU 900 EBR 0029Z
 0H500018
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-201
 0D1 000.0 WL 10
 0D1 001.4S1MS 0804
 0D1 001.4S2DES 30
 0D1 002.9F1MS 0804
 0D1 002.9F2DES 30
 0D1 002.9 MH R-181
 0D10034 002.9 FH

0H1C33986/AN R-180 X 149
 0H21011070543 RUE DALHOUSIE
 CITY OF MONTREAL
 0H3R-181 R-180
 0H4CU 900 EBR 0116Z
 0H500018
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-181
 0D1 000.0 WL 10
 0D1 000.1S1MS 0804
 0D1 000.1S2DES 30
 0D1 006.9 CN 30008 BLOCKED
 0D1 009.3 CNI 22503 0050LIVE
 0D1 010.2 CX 30008 SEALED OFF
 0D1 011.6 GO UNCHARTED MH
 0D1 011.6 SC CIRCULAR
 0D1 011.6 DC 600
 0D1 011.6 MC CONCRETE
 0D1 011.6F1MS 0804
 0D1 011.6C2DES 55
 0D1 011.6F2DES 55
 0D10075 011.6 SA DUE TO DES 55%

0H1C33986/AN R-180 X 150
 0H21011070556 RUE DALHOUSIE
 CITY OF MONTREAL
 0H3R-180 R-181
 0H4CD 900 EBR 0000Z
 0H5 NO ACCESS TO R-180
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-180
 0D1 000.0 WL 00
 0D10000 000.0 SA NO ACCESS R-180

0H1C33986/AN R-179 X 151
 0H21011070559 RUE DALHOUSIE
 CITY OF MONTREAL
 0H3R-179 R-180
 0H4CD 900 EBR 0000Z
 0H5 NO ACCESS TO R-179
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-179
 0D1 000.0 WL 00
 0D10000 000.0 SA NO ACCESS R-179

0H1C33986/AN R-196 X 152
 a1=MPEG_A_11102007_2125_156_2836i.mp2
 0H21011072115 RUE WELLINGTON
 CITY OF MONTREAL
 0H3R-199 R-196
 0H4CU 900 EBR 0019Z
 0H500018
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-199
 0D1 000.0 WL 05
 0D1 001.4S1MS 0804
 0D1 001.4S2DES 35
 0D1 001.9F1MS 0804
 0D1 001.9F2DES 35
 0D10035 001.9 SA DUE TO DES 35%

0H1C33986/AN R-199 X 153
 0H21011072132 RUE WELLINGTON
 CITY OF MONTREAL
 0H3R-199 R-200
 0H4CD 900 EBR 0019Z
 0H500018
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-199
 0D1 000.0 WL 05
 0D1 001.4S1MS 0804
 0D1 001.4S2DES 35
 0D1 001.4S3FL 12
 0D1 001.4S4DV 05
 0D1 001.9F1MS 0804
 0D1 001.9F2DES 35
 0D1 001.9F3FL 12
 0D1 001.9F4DV 05
 0D10033 001.9 SA DUE TO DES 35%

0H1C33986/AN R-196 X 154
 0H21011072214 RUE WELLINGTON
 CITY OF MONTREAL
 0H3R-196 R-199
 0H4CD 900 EBR 0000Z
 0H5 PARKED CARS
 0H6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-196
 OD1 000.0 WL 00
 OD10000 000.0 SA PARKCARS ON R-196

0H1C33986/AN R-197 X 155
 0H21011072216 RUE WELLINGTON
 CITY OF MONTREAL
 0H3R-197 R-196
 0H4CD 900 EBR 0244Z
 0H500018
 0H6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-197
 OD1 000.0 WL 05
 OD1 001.4S1MS 0705
 OD1 001.4S2DES 30
 OD1 001.4S3EL 0804
 OD1 003.9 MB 09
 OD1 009.3 MB 12
 OD1 009.3 DV 10
 OD1 014.0 DB 1101
 OD1 014.0 DV 10
 OD1 014.9 CX 22501
 OD1 021.6 CXI 22502 0025SEALED
 OD1 021.6F3EL 0804
 OD1 024.4 CXI 22504 0050SEALED
 OD1 024.4F1MS 0804
 OD1 024.4F2DES 30
 OD10082 024.4 SA DUE TO CXI

0H1C33986/AN R-197 X 156
 0H21011072233 RUE WELLINGTON
 CITY OF MONTREAL
 0H3R-197 R-198
 0H4CD 900 EBR 0058Z
 0H500018
 0H6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-197
 OD1 000.0 WL 05
 OD1 001.4S1MS 0804
 OD1 001.4S2DES 30
 OD1 004.2 MB 01
 OD1 005.8C2DES 40
 OD1 005.8F1MS 0804
 OD1 005.8F2DES 40
 OD10033 005.8 SA DUE TO DES 40%

0H1C33986/AN R-197 X 157
 a1=MPEG_A_11102007_2252_161_2891i.mp2
 0H2101107 RUE WELLINGTON
 CITY OF MONTREAL
 0H3R-198 R-197
 0H4CU 900 EBR 0069Z
 0H500018
 0H6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-198
 OD1 000.0 WL 05
 OD1 001.4S1MS 0804
 OD1 001.4S2DES 15
 OD1 001.4S3FL 12
 OD1 001.4S4DV 05
 OD1 003.1 CNI 22511 0075
 OD1 006.9 CNI 22501 0050LIVE
 OD1 006.9S5LL MARGINAL
 OD1 006.9F1MS 0804
 OD1 006.9F2DES 05
 OD1 006.9F3FL 02
 OD1 006.9F4DV 05
 OD1 006.9F5LL MARGINAL
 OD10053 006.9 SA SILTFINNARROWINVT

0H1C33986/AN r-199 X 158
 0H21011072331 RUE WELLINGTON
 CITY OF MONTREAL
 0H3R-200 R-199
 0H4CU 900 EBR 0000Z
 0H5 BLOCKING TRAFFIC 4 WAYS
 0H6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-200
 OD1 000.0 WL 00
 OD10000 000.0 SA BLOCKTRAFF 4 WAYS

0H1C33986/AN R-173 X 159
 0H21011072333 RUE NAZARETH
 CITY OF MONTREAL
 0H3R-174 R-173
 0H4CU 900 EBR 0000Z
 0H5 NO CAMERA ACCESS FROM MAIN
 0H6A1B AZ
 OD10000 000.0 ST
 OD1 000.0 MH R-174
 OD1 000.0 WL 00
 OD10000 000.0 SA

0H1C33986/AN R-168 X 160
 0H21011072339 RUE NAZARETH
 CITY OF MONTREAL
 0H3R-167 R-168
 0H4CU 900 600EBR 0001Z
 0H500018
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-167
 0D1 000.0 WL 10
 0D1 000.1 DES 90
 0D10024 000.1 SA DUE TO DES 90%

0H1C33986/AN R-166 X 161
 0H21011072345 RUE NAZARETH
 CITY OF MONTREAL
 0H3R-167 R-166
 0H4CU 900 600EBR 0001Z
 0H500018
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-167
 0D1 000.0 WL 00
 0D1 000.1 DES 90
 0D10010 000.1 SA DUE TO DES 90%

0H1C33986/AN R-167 X 162
 a1=MPEG_A_11102007_2349_166_2925i.mp2
 0H21011072349 RUE NAZARETH
 CITY OF MONTREAL
 0H3R-168 R-167
 0H4CU 900 600EBR 0001Z
 0H500018
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH
 0D1 000.0 WL 05
 0D1 000.1 DES 90
 0D10010 000.1 SA DUE TO DES 90%

0H1C33986/AN R-168 X 163
 0H21011072352 RUE NAZARETH
 CITY OF MONTREAL
 0H3R-168 R-169
 0H4CD 500 CCO 2500001Z
 0H500018
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-168
 0D1 000.0 WL 10
 0D1 000.1 DES 95
 0D10012 000.1 SA DUE TO DES 95%

0H1C33986/AN R-182 X 164
 0H21111070000 RUE BONNAVENTURE
 CITY OF MONTREAL
 0H3R-182 R-183
 0H4CD 500 CCO 2500000Z
 0H5
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-182
 0D1 000.0 WL 00
 0D10000 000.0 SA MHR-182ONOFFRAMP

0H1C33986/AN R-183 X 165
 0H21111070002 RUE BONNAVENTURE
 CITY OF MONTREAL
 0H3R-183 R-184
 0H4CD 500 CCO 2500000Z
 0H5 MH ON OFF RAMP
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-183
 0D1 000.0 WL 00
 0D1 000.0 SA MHR-183ONOFFRAMP

0H1C33986/AN R-183 X 166
 0H21111070003 RUE BONNAVENTURE
 CITY OF MONTREAL
 0H3R-184 R-183
 0H4CU 500 CCO 2500000Z
 0H5 UNABLE TO LOCATE IN MH R-184
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-184
 0D1 000.0 WL 00
 0D10000 000.0 SA UNABLETOFIND LINE

0H1C33986/AN 303-40-022X 167
 0H21111070109 SAINT ANTOINE
 CITY OF MONTREAL
 0H3303-40-021 303-40-022
 0H4CU1500 750EBR 2500319Z
 0H500018
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-40-021
 0D1 000.0 WL 10
 0D1 001.5 GO STEEL LINED
 0D1 009.8 CN 30001 LIVE
 0D1 021.4 LL SLIGHT
 0D1 031.8 DES 25
 0D10075 031.8 SA DUE TO DES 25%
 0D1 031.9 GO UNCHARTMH CARPARK

0H1C33986/AN 303-40-022X 168
 0H21111070134 SAINT ANTOINE
 CITY OF MONTREAL
 0H3303-40-022 303-40-021
 0H4CD1500 750EBR 2500000Z
 0H5
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH 303-40-022
 0D1 000.0 WL 40
 0D10000 000.0 SA NEEDS CLEANING

0H1C33986/AN R-102 X 169
 0H21111070159 SAINT ANTOINE
 CITY OF MONTREAL
 0H3R-101 R-102
 0H4CU750 CCO 2500248Z
 0H500018
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-101
 0D1 000.0 WL 10
 0D1 001.5S1DE 05 RUBBLE
 0D1 012.2 CX 22510 LIVE
 0D1 012.7 CX 22511
 0D1 015.5F1DE 05 RUBBLE
 0D1 020.2 CNI 15002 0075LIVE
 0D1 022.1 CNI 30010 0050LIVE
 0D1 024.8 MH R-102
 0D10044 024.8 FH

0H1C33986/AN R-100 X 170
 0H21111070222 SAINT ANTOINE
 CITY OF MONTREAL
 0H3R-101 R-100
 0H4CU750 CCO 2500000Z
 0H5 NO ACCESS FROM MH R-101
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-101
 0D1 000.0 WL 05
 0D10000 000.0 SA NOACC HIGHINWALL

0H1C33986/AN R-100 X 171
 0H21111070223 SAINT ANTOINE
 CITY OF MONTREAL
 0H3R-100 R-101
 0H4CD750 CCO 2500000Z
 0H5
 0H6A1B AZ
 0D10000 000.0 ST
 0D1 000.0 MH R-100
 0D1 000.0 WL 05
 0D10000 000.0 SA PARKCARONMHR-100
 ZZZ